

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
NINETEENTH SET OF INFORMATION REQUESTS FROM THE ATTORNEY
GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: John E. Skirtich, Consultant (Revenue Requirements)

AG-19-35 Referring to the Company's response to Information Request AG-1-90, please itemize and quantify any Outside Service allocated to Bay State Gas that cost the NCSC \$500,000 or more during 2004. Please also provide a detailed description of the particular services provided during the test year.

Response: NCSC did not have any charges greater than \$500,000 for Outside Services that were allocated to Bay State Gas during the test year.

.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM ATTORNEY GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-21-1 Provide a list identifying any meter reading inaccuracies associated with the Metscan devices. The list should identify the magnitude of the inaccuracies by class and include dates corresponding to the inaccurate recordings as well as dates the associated billing adjustments were made. Provide all work papers, calculations and assumptions relating to the corresponding billing adjustments necessary to account for such inaccurate recordings.

Response: The Company does not have a readily-available list of reading inaccuracies associated with the Metscan devices. As a general matter, Metscan's principal problem was not meter reading accuracy. Rather, some Metscan devices, particularly those devices located on outside meters that had been in the field for more than seven years, failed to provide any meter reading. Other Metscan devices failed to provide meter readings due to problems with the telephone connection.

The Company is investigating the ability to develop an ad hoc query of the Customer Information System to determine if some information can be extracted relative to meter reading inaccuracies. This information will be provided, if and when it becomes available.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM ATTORNEY GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-21-2 Please provide copies of all correspondence and reports associated with
Metscan meter reading inaccuracies that the Company has filed with the
Department and any associated Department Orders.

Response: The Company is unable to locate any reports filed with the Department
regarding Metscan meter reading inaccuracies. As stated in the
Company's response to AG-21-1, the failure of some units to provide any
meter reading, either due to weather damage or to telephone line
connection problems, represented the most significant problem
associated with the Metscan system.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM THE ATTORNEY
GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-21-3 Provide a list and description of customer complaints as well as any
refunds associated with Metscan, including reimbursement of telephone
bills.

Response: Attachment AG-21-3 is a list of refunds to customers for telephone line
repairs associated with the installation/removal of Metscan devices. The
list covers the period March 2002 to present.

Bay State Gas Company
Customer Payments for Telephone Line Repairs
Associated With Metscan

03/31/02	18583JOHN VARANE	\$82.50
04/25/02	18694GEORGE CELORIER	\$82.50
04/29/02	18708HEATHER SCHLEIFF	\$82.50
04/08/02	18657DONALD DEBONA	\$82.50
04/05/02	18642John Clearly	\$82.50
04/08/02	18658BEVERLY CRAIG	\$82.50
04/25/02	18697PEREIRA MANUEL	\$120.00
04/16/02	18672KENNISTON, JOHN	\$82.50
04/08/02	18660TRACY CAPONE	\$82.50
04/16/02	18673BEVERLY CRAIG	\$37.50
04/08/02	18654DAVID BAKER	\$82.50
04/08/02	18656JAY'S BEAUTY SALON	\$82.50
04/08/02	18641Robert Besse	\$82.50
04/08/02	18655ROBERT HYNES	\$120.00
04/08/02	18659KENENTH BENTON	\$82.50
04/18/02	18679THOMAS BALDASANE	\$82.50
04/18/02	18678ALVES JOSEFA	\$82.50
04/25/02	18692JOSE SANTOS	\$82.50
04/25/02	18695PETER MCHUGH	\$82.50
04/29/02	18707SUSAN McCARTHY	\$82.50
04/29/02	18706MICHAEL REGAN	\$82.50
04/25/02	18693MARY WHITING	\$82.50
04/18/02	18677ROBERT W. VANHESS	\$82.50
04/25/02	18698DIMITRIOS EXARHOPOULO	\$120.00
04/18/02	18676MONIQUE JANKOWSKI	\$82.50
04/25/02	18691ROSE PENNY	\$202.50
05/30/02	18784GASPER GRILLO	\$82.50
05/21/02	18754WAYNE VERGAS	\$82.50
05/23/02	18775JOHN PARRIN	\$82.50
05/30/02	4108MICHAEL GULLBRANTS	\$117.11
05/21/02	18750SHARON GIFFORD	\$82.50
05/23/02	18770THOMAS DOUCETTE	\$82.50
05/21/02	18755FRANK REICH	\$82.50
05/21/02	18753ANNE JENKINS	\$82.50
05/23/02	18771NATALYA TUROVA	\$82.50
05/30/02	18785EDWARD ECCLESTONE	\$120.00
05/21/02	18749J.A.CANTEEN CO.	\$82.50
05/21/02	18751WILLIAM KELLY	\$120.00
05/30/02	18783LAWRENCE WHALEN II	\$82.50
05/07/02	18727ALAN KANNALLY	\$82.50
05/07/02	18725JUMP FOR JOY INC.	\$120.00
05/21/02	18752ROSEMARY LINCOLN	\$120.00
05/07/02	18726STEVEN ELLIS	\$82.50
05/21/02	18756DEBRA DECOSTE	\$82.50
06/30/02	18824PHILLIP CAPERNAROS	\$120.00
06/30/02	18847STOUGHTON TOWN SPA	\$75.00
06/11/02	18756DEBRA DECOSTE	\$37.50
06/11/02	18804JOHN CATALANO	\$82.50

Bay State Gas Company
Customer Payments for Telephone Line Repairs
Associated With Metscan

06/30/02	18841DIXIE LEVESQUE	\$82.50
06/11/02	18803IRVING DEMBLING	\$82.50
06/30/02	18840DAVID GOODMAN	\$82.50
06/30/02	18842HESSCO	\$82.50
06/30/02	18843LAUREEN HOUSE	\$82.50
06/30/02	18825ALBERT FARIA	\$120.00
06/11/02	18809DENISE RAYNARD	\$82.50
06/11/02	18808GUY WOOLLARD	\$85.00
06/11/02	18807PATRICIA GRIFFIN	\$157.50
06/11/02	18806ERIC BINDMAN	\$200.00
06/11/02	18805RICHARD GIRAGOSIAN	\$95.00
07/31/02	18915BRIAN SMITH	\$82.50
07/31/02	18929GLENN JACKSON	\$82.50
07/31/02	18931SOLOMAN COHEN	\$82.50
07/31/02	18930MEGAN HOTCHKISS	\$115.00
07/31/02	18872THEODORE HAINES	\$82.50
07/31/02	18913DIANE GOODALE	\$82.50
07/31/02	18932PATRICIA JENKINS	\$82.50
07/01/02	18864DANIEL BAKER	\$120.00
07/01/02	18865MICHAEL MATHIAS	\$82.50
07/31/02	18914MARCIA SULLIVAN	\$115.00
07/31/02	18912TERRI HOWIE	\$82.50
07/01/02	18862STEVEN WHALEN	\$82.50
07/31/02	18911JERI KATZ	\$82.50
07/01/02	18867PETER WOLCZIK	\$82.50
07/01/02	18863HENRY HAWLAND	\$82.50
07/31/02	18800DIANA ABBASY	\$82.50
07/31/02	18933JOANNE SHADRICK	\$82.50
07/01/02	18869KAREN OLSON	\$82.50
07/31/02	18798POWERS & LIQUORI	\$82.50
07/31/02	18799SUSANNE CURTIS	\$82.50
07/31/02	18908DONNA ROBICHEAU	\$82.50
07/01/02	18866KATHLEEN EVANS	\$82.50
08/31/02	18981RUTH HALL	\$82.50
08/31/02	18971FRED DAMON	\$120.00
08/31/02	18983ARTHUR MAYER	\$82.50
08/31/02	18949C.B. Hutchinson	\$82.50
08/31/02	18975JEFF PEARLSTEIN	\$82.50
08/31/02	18982BRUCE PRIXTER	\$82.50
08/31/02	18973MARK OSBORNE	\$82.50
08/31/02	18974DANIEL SCHUSTER	\$82.50
08/31/02	18952SUZANNE FINKEL	\$82.50
08/31/02	18984DAVID VEDOVELLI	\$82.50
08/31/02	18978VINCENT TSANG	\$82.50
08/31/02	18946JOSEPH OSHRY	\$82.50
08/31/02	18977JANICE MECHAN	\$82.50
08/31/02	18972RICK TEIXEIRA	\$82.50
08/31/02	18976JEANETTE BLACKER	\$120.00

Bay State Gas Company
Customer Payments for Telephone Line Repairs
Associated With Metscan

09/30/02	19042RICHARD JUSTINO	\$82.50
09/30/02	19043BENJAMIN COOLEY	\$82.50
09/30/02	19041ALETHA THOMPSON	\$82.50
09/30/02	19006BARBARA MURPHY	\$120.75
09/30/02	19040MARIA TAVARES	\$82.50
09/30/02	19005RONALD PORAT	\$82.50
10/31/02	19095DARLENE COSTA	\$82.50
10/31/02	19094KAREN DOUGHTY	\$82.50
10/31/02	19107SARNATECH BNE	\$120.00
10/31/02	19099EDWARD SPRINGHETTO	\$82.50
10/31/02	19101PEARL HEMEON	\$82.50
10/31/02	19100EILEEN & ROBERT WELCH	\$82.50
10/31/02	19098RICHARD SPITZBERG	\$82.50
10/31/02	19102CHARLES FARLING	\$82.50
10/31/02	19097FRED POTOZAK	\$82.50
10/31/02	19096ROXANNE YOUNG	\$82.50
11/30/02	19158JOHN POWERS	\$82.50
11/30/02	19160ELIZABETH DAVIDSON	\$82.50
11/30/02	19159McNAMARA FARMS	\$120.00
11/30/02	19161RICHARD GATELY	\$120.00
11/30/02	19154BEAUTIFUL HAIR	\$120.00
11/30/02	19156LEO SPIEGEL	\$82.50
11/30/02	19155THEODORE URBAN	\$82.50
11/30/02	19157KATHLEEN BENSON	\$120.00
12/31/02	3647WILLIAM FOSKITT JR	\$99.61
12/31/02	19193RICHARD HEWITT	\$82.50
12/31/02	19259DENNIS SULLIVAN	\$250.00
12/31/02	19226HAROLD HERSH	\$82.50
12/31/02	19225MATTHEW ANGLIN	\$82.50
12/31/02	19194JOSE' ANDRADE	\$82.50
12/31/02	19223NOELIA M. FREITAS	\$82.50
12/31/02	19224KATHIE DULLEA	\$82.50
01/31/03	19363WINTHROP STREET MOTOR	\$120.00
01/31/03	19280DENNIS KRAEZ	\$82.50
01/31/03	19279GEZINA SHANK	\$120.00
01/31/03	19369BRIAN GAUDREAU	\$120.00
01/31/03	19368PAUL KENNEDY	\$82.50
01/31/03	19367SCOTT COWPER	\$16.99
01/31/03	19281D.J. LOONEY	\$157.50
01/31/03	19362SARA KAUFMAN	\$82.50
01/31/03	19366NANCY DESROCHERS	\$82.50
01/31/03	19279GEZINA SHANK	\$120.00
01/31/03	999161704LAWRENCE WILLIAM	\$82.50
01/31/03	19282GEORGE CALKINS	\$82.50
01/31/03	19364LYNN JOHNSON	\$82.50
01/31/03	19283ANTHONY CELIA	\$85.00
01/31/03	19278JOHN E. FRIEDMAN	\$82.50
01/31/03	19277SUBHASH C. CHUGH	\$82.50

Bay State Gas Company
Customer Payments for Telephone Line Repairs
Associated With Metscan

02/28/03	19419ISAURA AMARAL	\$82.50
02/28/03	19438SHEILA SCHAMBER	\$95.00
02/28/03	19425MEDRICK LAFLEUR	\$82.50
02/28/03	19439A-1 LOCK & KEY	\$82.50
02/28/03	19440MARY ANN TORRES	\$120.00
02/28/03	19418DANIEL HAYES	\$82.50
02/28/03	19475FIRST BAPTIST CHURCH	\$82.50
02/28/03	19474ROBERT NICHOLS	\$123.45
02/28/03	19473VICTOR LEWIS	\$82.50
02/28/03	19472CARL LUNDIN	\$16.99
02/28/03	19422CLAUDINE RASCHI	\$82.50
02/28/03	19471COUNTRY COTTAGE CHILD	\$82.50
02/28/03	19470IRENE SHEA	\$82.50
02/28/03	19437ELIZABETH METZLER	\$82.50
02/28/03	19441MARC SABINE	\$82.50
02/28/03	19426RICHARD LEEMAN	\$82.50
02/28/03	19416HUGH FLANAGAN	\$83.00
02/28/03	19421KEITH LASTER	\$82.50
02/28/03	19417VICTORIA RAWLINSON	\$82.50
02/28/03	19469MARK KALUZNY	\$82.50
02/28/03	19442ROBERT ALEXANDER	\$82.50
02/28/03	19423DON CORRIVEAU	\$82.50
02/28/03	19424LEWIS W. ROSATI	\$87.50
02/28/03	19420JULIE O'BRIEN	\$115.19
03/31/03	19493PRIMITIVE LEATHER	\$84.19
03/31/03	19490LORI COSTELLA	\$82.50
03/31/03	19536DONALD BERGQUIST	\$91.00
03/31/03	19537LOUISE TODD	\$82.50
03/31/03	19540RONNIE LEAVITT	\$82.50
03/31/03	19496CATHY DiMUZIO	\$90.00
03/31/03	19491ROBERT WASZKIEWICZ	\$82.50
03/31/03	19495NORTON PROMAN	\$120.00
03/31/03	19535PAT KNIGHT	\$82.50
03/31/03	19538LAUREN KUEHL	\$82.50
03/31/03	19539KEILINE LAZARE	\$82.50
03/31/03	19541WEXLER'S	\$91.00
03/31/03	19542HERB LYKER	\$150.00
03/31/03	19492FELICIA FARRAR	\$82.50
03/31/03	19365CHICOPEE NURSING HOME	\$82.00
03/31/03	19494LINDA HOOKER	\$82.50
05/31/03	19624RUTH RUBINO	\$90.00
05/31/03	19625ANN RODGERS	\$91.00
05/31/03	19626AL LAUREANO	\$91.00
05/31/03	19645NANCY MACKENZIE	\$123.52
05/31/03	19623ANTONIO GOMES	\$91.00
05/31/03	19620GAIL BARSZEZ	\$91.00
05/31/03	19622SUZANNE GARBER	\$91.00
05/31/03	19621LOULA SANTANGELO	\$82.50

Bay State Gas Company
Customer Payments for Telephone Line Repairs
Associated With Metscan

06/30/03	19710SCOTT & MARIA KOLLAR	\$91.00
06/30/03	19709ROBERT MARSHALL	\$137.00
06/30/03	19688GEORGE SOLOMON	\$82.50
06/30/03	17866THOMAS BONAMICI	\$91.00
06/30/03	16928VERIZON WIRELESS	\$25.55
06/30/03	19685KENT TARRANT	\$91.00
06/30/03	19706SELMA MALTZMAN	\$91.00
06/30/03	19687JEAN HOBAN	\$16.99
06/30/03	19691KIM RODRIGUEZ	\$91.00
06/30/03	19708JOHN F. TAYLOR	\$91.00
06/30/03	19621LOULA SANTANGELO	\$82.50
06/30/03	19686SALVATORE TRIOLA	\$91.00
06/30/03	19690DAN RONCALLI	\$87.70
06/30/03	19705STEPHANIE T. BAXENDAL	\$91.00
06/30/03	19707NORMAN GONTHIER	\$91.00
06/30/03	19711W. J. PULEO	\$137.00
06/30/03	19712ELIZABETH BARRY	\$91.00
06/30/03	19689GEOPHYSICAL APPLICATI	\$76.50
07/31/03	19756MICHAEL G. AFTOSMES,	\$137.00
07/31/03	19734HENRY MOSCA	\$91.00
07/31/03	19736RUTH E. YOUNG	\$91.00
07/31/03	19738CANTON ST. MINI STORA	\$91.00
07/31/03	19740MARK BELL	\$91.00
07/31/03	19735SHIRLEY GILBERT	\$91.00
07/31/03	19737THIEU DUONG MD.MPH	\$91.00
07/31/03	19757JAMES J. ARMSTRONG	\$91.00
07/31/03	19755D.J. MOITOZA	\$91.00
07/31/03	19739JEAN WISNIEWSKI	\$91.00
08/31/03	19807JAMES & JEAN GRIECO	\$137.00
08/31/03	19813GALLERANI ELECTRIC CO	\$75.00
08/31/03	19814PATRICIA & JOHN SHIPP	\$91.00
08/31/03	19815VICTOR POITRAS	\$104.99
09/30/03	19843MARK A. VESS	\$91.00
09/30/03	19850HAPCO AUTO PARTS	\$91.00
09/30/03	19845EUGENE KAPPER	\$91.00
09/30/03	19846SCOTT RUDENSTEIN	\$16.99
09/30/03	19851KEN MAFFEI	\$91.00
09/30/03	19854STELLA MORRISON	\$91.00
09/30/03	19853SUZANNE LOVE	\$91.00
09/30/03	19849ELINOR L. AUSTIN	\$91.00
09/30/03	19930JAMES SEMPLE	\$91.00
09/30/03	19932DORIS COLLINS	\$91.00
09/30/03	19934MARY SOUZA	\$91.00
09/30/03	19928DAVID COLLINS	\$137.00
09/30/03	19931HENRIETTA SINHA	\$137.00
09/30/03	19844JOSEPH SOUZA	\$91.00
09/30/03	19847VERIZON	\$91.00
09/30/03	19848DANIEL FANTONI JR	\$91.00

Bay State Gas Company
Customer Payments for Telephone Line Repairs
Associated With Metscan

09/30/03	19852ROBB BRUCE	\$91.00
09/30/03	19893SERGEY SMIRNOV	\$91.00
09/30/03	19894DAVID A. COUTURE	\$91.00
09/30/03	19929EDWARD CORR	\$91.00
09/30/03	19933PATRICIA SOUZA	\$91.00
10/31/03	19949RUTH JAMES	\$132.50
10/31/03	19948ROBERT J. PAQUETTE	\$91.00
10/31/03	19950GREAT CHINA RESTAURAN	\$91.00
10/31/03	19976JOHN PARZIALE	\$137.00
10/31/03	19975JOHN CUGINI	\$91.00
10/31/03	19974R. PRASAD DASARI	\$137.00
11/30/03	20056PATRICIA CARROLL	\$91.00
11/30/03	19990LAURIE SOUZA	\$91.00
11/30/03	19996EDWARD V. PUOPOLO	\$91.00
11/30/03	20055ANTHONY CENTORE	\$91.00
11/30/03	20002ERIC DAHL	\$91.00
11/30/03	19989LINDA SCIBELLI	\$137.00
11/30/03	19991SHONNA'S GOURMET GOOD	\$263.00
11/30/03	19995JANE PLUMB	\$94.00
11/30/03	19994DENISE ROOSA	\$91.00
11/30/03	19993HOGAN COMMUNICATIONS,	\$225.00
11/30/03	19992SERGEY SMIRNOV	\$91.00
11/30/03	19998KAREN DOYLE	\$91.00
11/30/03	20050LEO J. TETRAULT	\$91.00
11/30/03	20051DORIS PETRUCCI	\$95.00
11/30/03	19997LINDA LINEHAN	\$137.00
11/30/03	19999BARRY GREENE	\$91.00
11/30/03	20000MARY BLACKMAN	\$91.00
11/30/03	20054CROTEAU PLUMBING	\$91.00
11/30/03	20053THOMAS DEVELIN	\$82.50
11/30/03	20052ELAINE PANOS	\$90.00
11/30/03	20001JANICE HURLEY	\$113.60
11/30/03	20057KAREN BRITT	\$82.50
12/31/03	20120RONNIE LAMONTAGNE	\$91.00
12/31/03	20093JOSEPH ALLEN	\$91.00
12/31/03	20122STEPHEN NASSON	\$180.00
12/19/03	20055ANTHONY CENTORE	-\$91.00
12/31/03	20121LAURA MCHUGH	\$95.00
12/31/03	20123RONGJUN XU	\$91.00
12/31/03	20124DEBORAH BUEBENDORF	\$91.00
01/31/04	20167WILLIAM PIGOTT	\$91.00
01/31/04	20181R PICARD	\$91.00
01/31/04	20183JAMES CIPOLLA	\$91.00
01/31/04	20182JOHN HESS	\$137.00
01/31/04	20170MANUEL FARIA	\$91.00
01/31/04	20171JOAQUIM CARREIRA	\$91.00
01/31/04	20172WILLIAM BURROWS	\$91.00
01/31/04	20168ELEANOR OCKERT	\$91.00

Bay State Gas Company
Customer Payments for Telephone Line Repairs
Associated With Metscan

01/31/04	20180MICHAEL GRUPPOSO	\$263.71
01/31/04	20169JEAN GERRIOR	\$120.00
02/29/04	20223JOHN HARUI INC	\$91.00
02/29/04	20222RON PEDERZANI	\$90.00
02/29/04	20221TED CREVIER	\$91.00
02/29/04	20228LORRAINE WOODS	\$225.00
02/29/04	20227RANDY FROMKIN	\$91.00
02/29/04	20247WILLIAM KIRBY	\$91.00
02/29/04	20229MICHELLE GRABERT	\$137.00
02/29/04	20226AMY PIELA	\$91.00
02/29/04	20224CYNTHIA MASON	\$137.00
02/29/04	20246ANTHONY GIUFFRE	\$255.00
02/29/04	20225THERESA GODDARD	\$91.00
02/29/04	20249PAUL GEORGE JR	\$91.00
02/29/04	20248SYDNEY HYMAN	\$91.00
03/31/04	20308JOSEPH NASUTI	\$91.00
03/31/04	20291GARY BOUSQUET	\$91.00
04/30/04	20354MARY WILLIAMS	\$91.00
04/30/04	20355SUSAN WOLK	\$91.00
04/30/04	20353ROY YARNELL	\$91.00
04/30/04	20351GEORGE LAFLAMME	\$147.50
04/30/04	20315DAVID FAZIO	\$91.00
04/30/04	20352ROBERT TEGHTSOONIAN	\$91.00
05/31/04	20390JAIME GONCALVES	\$229.00
05/31/04	20389RONALD THIBERT	\$91.00
05/31/04	20393CLAIRE MALLETTE	\$50.00
05/31/04	20391JULIE MCDERMOTT	\$425.00
05/31/04	20386GREG WHITE	\$170.00
05/31/04	20384MARIE STEPTOE	\$91.00
05/31/04	20383ROBERT WATSON	\$91.00
05/31/04	20385JOEL ANGELICO	\$91.00
05/31/04	20387KIM CASEY	\$91.00
05/31/04	20388GERALD WRIGHT	\$137.00
05/31/04	20392PETER PALUZZI	\$91.00
06/30/04	20429BEVERLY BAIARDI	\$82.50
06/30/04	20428JOHN MULVEY	\$91.00
06/30/04	20475WILLIAM DUNHAM JR	\$120.00
06/30/04	20473KATHLEEN BEATTIE	\$91.00
06/30/04	20431ANDRZEJ DANUTA KORCZ	\$91.00
06/30/04	20430WALTER CHACE	\$91.00
06/30/04	20427PAULA DEPIERRO	\$91.00
06/30/04	20433DOMENIC TIBERI	\$110.00
06/30/04	20474TREMONT LIQUORS & WIN	\$91.00
06/30/04	20432FRANCES AROOTH	\$91.00
06/30/04	20472JOSEPH GRANDE	\$600.00
06/30/04	20434ARTHUR GOOLET	\$19.99
07/31/04	20513RICHARD LUNDELL	\$91.00
07/31/04	20514GAIL SYRIALA	\$375.00

Bay State Gas Company
Customer Payments for Telephone Line Repairs
Associated With Metscan

07/31/04	20518ROBERT SMITH	\$110.00
07/31/04	20516MARIANNE SARAZEN LONA	\$91.00
07/31/04	20517CYNTHIA LONCAR	\$91.00
07/31/04	20515JILL CONROY	\$110.00
08/31/04	20529ANDREA SLOBODKIN	\$137.00
08/31/04	20530LAPRADE KEN	\$202.00
08/31/04	20539SUSAN DRAPEAU	\$137.00
09/30/04	20600JOSEPH CORRELA	\$91.00
09/30/04	20599JOANNE EVERY	\$91.00
09/30/04	20601VINCENT MARIANO	\$82.50
09/30/04	20603JOANNE WAKEFIELD	\$91.00
09/30/04	20595STEPHEN WYMAN	\$91.00
09/30/04	20597PAUL DEEB	\$91.00
09/30/04	20598MARGARET DOWNEY	\$95.00
09/30/04	20596CHENG MING TSENG	\$142.50
09/30/04	20602LEON HALIO	\$91.00
10/31/04	20718JOHN KING	\$91.00
10/31/04	20707JESS HILL	\$125.00
10/31/04	20712FLORENCE SHEA	\$91.00
10/31/04	20710STEPHEN WIRZBURGER	\$91.00
10/31/04	20714STEVEN LEBOW	\$75.00
10/31/04	20719CAROL LEET	\$91.00
10/31/04	20709CHERYL FERRARA	\$91.00
10/31/04	20715RICHARD CADIEUX	\$91.00
10/31/04	20713JANE NEERGHEEN	\$137.00
10/31/04	20711RAYMOND CHRISTOPHER	\$60.00
10/31/04	20716ROBERT LYNCH	\$149.82
10/31/04	20720ALAN AND LINDA KIPETZ	\$182.41
10/31/04	20708JEROME SATKOS	\$91.00
10/31/04	20717PHILLIP GRABLE	\$91.00
11/30/04	20797HOLY GHOST BROTHERHOO	\$137.00
11/30/04	20745JAMES DOMALDO	\$91.00
11/30/04	20798RICHARD MALMBERG	\$137.00
11/30/04	20795ARTHUR WEBB	\$19.99
11/30/04	20747SCOTT SPROVIENO	\$91.00
11/30/04	20799RAYMOND THERRIEN	\$91.00
11/30/04	20743MARIA RODRIGUEZ	\$82.50
11/30/04	20744ARLINDO ALVES	\$137.00
11/30/04	20801PETER BOREY	\$137.00
11/30/04	20741DIANE RANALDI	\$324.45
11/30/04	20742PHOEBE BROWN	\$91.00
11/30/04	20800RICHARD M OSGOOD	\$91.00
11/30/04	20746RONALD NICKLES	\$229.00
11/30/04	20738DAVID CONTOIS	\$259.00
11/30/04	20739ALFRED DEYO	\$110.00
11/30/04	20802MICHAEL THIBODEAU	\$91.00
11/30/04	20740STEPHEN HAWKINS	\$91.00
11/30/04	20796BILL SWANSON	\$135.00

Bay State Gas Company
Customer Payments for Telephone Line Repairs
Associated With Metscan

12/31/04	20867MICHAEL WEEKES	\$91.00
12/31/04	20865SHEILA BRODERICK	\$91.00
12/31/04	20868RONALD BERKOWITZ	\$248.00
12/31/04	20864EDWARD ANTOSZ	\$165.00
12/31/04	20862NANCY MCKAY	\$279.50
12/31/04	20866SHEILA AND DAVID SAVA	\$216.00
12/31/04	20861URSULA AND JAME MCQUI	\$91.00
12/31/04	20869COLLEEN MAGUIRE	\$91.00
12/31/04	20863PATRICIA GOSSELIN	\$91.00
12/31/04	20860PHILIP REED	\$91.00
01/31/05	20906JEFF CHANIN	\$81.50
01/31/05	20905LOUIS GREENWOOD	\$91.00
01/31/05	20908ELEANOR BRACKETT	\$91.00
01/31/05	20910LOUISA MCCANN	\$91.00
01/31/05	20909MARY MACKINNON	\$91.00
01/31/05	20907THOMAS E SAWRAN	\$225.00
02/28/05	20939JOHN BOUCHARD	\$92.00
02/28/05	20957AMY HALE	\$91.00
02/28/05	20958JULIE PIERCE	\$91.00
02/28/05	20938DAVID BELCHER	\$91.00
02/28/05	20978WILL CUNNINGHAM	\$102.00
02/28/05	20980CHARLES LEWIS	\$91.00
02/28/05	20977DONNA YVON	\$91.00
02/28/05	20979ROBERT MULLALY	\$137.00
02/28/05	20959LILLIAN NUBILE	\$91.00
02/28/05	20940ROSE LAMARCA	\$137.00
02/28/05	20981GILBERT CAMPOS	\$91.00
02/28/05	20931SHILIANG ZHOU	\$91.00
03/31/05	20996ELIZABETH SILVIA	\$91.00
03/31/05	21046CHRIS POOLE	\$91.00
03/31/05	21024BRUCE GERMINARO	\$91.00
03/31/05	20998MEMORY LANE CONSIGNME	\$91.00
03/31/05	20999REVEREND JOHN KIRAMAR	\$91.00
03/31/05	21025JOAO JORGE	\$91.00
03/31/05	20995ROBERT GARNEAU	\$137.00
03/31/05	20997NORFOLK CO RETIREMENT	\$120.00
04/30/05	21068PATRICIA FLAHERTY	\$91.00
04/30/05	21086ANGELO MANCHINO	\$137.00
04/30/05	21087ATLEE CORPORATION	\$266.25
04/30/05	21088EUGENE FOLEY	\$91.00
04/30/05	21067JOHN DAVIES	\$137.00
05/31/05	21145DAVID LUIS	\$91.00
05/31/05	21147HOLLY MARTINEAU	\$135.00
05/31/05	21146MARTHA MAHONEY	\$135.00
		\$43,825.24

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM ATTORNEY GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-21-4 Regarding the functionality of Metscan, explain how often the device transmits information and whether the device interrupts the customer's telephone/internet service.

Response: The frequency of transmission is a function of how the device is programmed. For instance, for monthly meter reading purposes, the device is programmed to call once per month.

Regarding interruption of telephone/internet service, the device will not attempt a call if it does not detect a telephone dial tone.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM ATTORNEY GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-21-5 Identify the costs associated with the transmission of information over the phone line and whether the customer pays for the associated costs. Identify any circumstances which would cause the customer to pay long distance services for the use of this device.

Response: Generally, there is no telephone cost to the customer, as the call is made to a toll free number. The Company was made aware of one very unusual instance with one residential customer that the outbound call from the Metscan device did impact the customer's telephone bill.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM ATTORNEY GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-21-6 Refer to AG -3-32(b), p. 9. The Company states that the average volume of long reads and customer complaints over the past 2 years was 15,777, giving a total average cost of \$346,606. Please provide all workpapers, calculations and assumptions used by the Company to calculate these numbers.

Response: The information provided in AG-3-32 (b), page 9 was compiled in 2000 and covered 1998 - 1999. The Company is unable to locate the back-up documentation for this data.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM THE ATTORNEY
GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-21-7 Please provide a chart depicting the number of long reads, re-reads and customer complaints and associated costs since the deployment of Metscan devices.

Response: The Company does not maintain data for long reads, re-reads and customer complaints that are specifically related to Metscan devices. The information discussed @ p. 9 of AG-3-32 (b) is related to the general Job Code 1650 and was intended to demonstrate that one of the advantages of the Metscan technology is that it could eliminate the need for some special service trips for re-reads.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM ATTORNEY GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-21-8 Refer to AG-3-32(b), p. 12. The Company lists an Itron charge and desktop fixes under O&M related costs. Please explain what these costs entail.

Response: The Company surmises that the Itron charge is the cost of the maintenance agreement for software. The term "desktop fix" refers to a correction of administrative information, such as correcting a Metscan device number or meter number so that a Metscan reading can be properly associated with a meter.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM ATTORNEY GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant

AG-21-10 Refer to AG-3-32 (b), p. 14 and the Company's response to AG-03-33. On what basis did the Company believe that the installation is assumed to last 42 years given that the Metscan devices were purchased with a standard one year warranty.

Response: AG-3-32 (b), p. 14 illustrates two estimated cost scenarios of reading a customer's meter over a 42-year period. Neither scenario assumes a device life of 42 years. The first scenario assumes a device life of 21 years, while the second scenario assumes a 7-year life for the device.

Regarding the warranty, the length of a warranty is not necessarily intended to represent the expected life of the product. For instance, consumer products such as refrigerators carry one-year warranties, but a reasonable life expectancy for the product is significantly longer.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY FIRST SET OF INFORMATION REQUESTS FROM ATTORNEY GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-21-11 Refer to AG-3-32(b), p. 15. The Company identifies the no call rate as 17.3%. Define the no call rate and provide all workpapers, calculations and assumptions employed by the company to calculate this percentage.

Response: The no call rate is the percent of devices in the field that fail to transmit a meter reading to the Company's meter reading system.

The study provided at AG-3-32(b) was prepared in 2000 and the work papers have not been located.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
FIFTEENTH SET OF INFORMATION REQUESTS FROM THE D.T.E.
A.G.-22-17

Date: June 27, 2005

Responsible: Stephen H. Bryant, President

AG-22-17 Is the use of "Cromwell Waivers" standard practice in Massachusetts? What other Massachusetts LDCs use Cromwell Waivers? Please provide a copy of a Cromwell Waiver. Is this a standard form? If not, please explain what specific language or characteristics make-up such a document. Has the Department explicitly approved the use by any LDC of Cromwell Waivers?

Response: To the best of the Company's knowledge, the use of "Cromwell Waivers" is standard practice by LDCs in Massachusetts.

The following Massachusetts LDCs use Cromwell Waivers:

- Fitchburg Gas & Electric Light Company
- New England Gas Company
- Blackstone Gas Company
- Keyspan Energy Delivery
- Holyoke Gas & Electric
- Berkshire Gas Company.

Attachment AG-22-17 is the standard Cromwell Waiver form used by the Company.

While the Company is not aware of a Department order explicitly approving the use of Cromwell Waivers, the Department is well aware of this long standing practice, and the use of Cromwell Waivers is entirely consistent with Massachusetts law. Specifically, under Massachusetts General Law Chapter 164, Section 125, utilities may refuse to initiate service to a customer where such customer has an unpaid balance with such utility at a previous service location. The Cromwell Waiver allows a customer, who has an amount owing to a utility for service at a prior service address, to initiate service at a new service address, while preserving the utility's right to collect a valid debt outstanding from such customer.



2025 Roosevelt Avenue
P.O. Box 2025
Springfield, MA 01102-2025

CROMWELL WAIVER

Attention: Credit Department

I, _____, accept responsibility for an arrearage of \$ _____ incurred under acct. number _____, at _____

I understand that Bay State Gas Co. will transfer this amount into account number _____ in my name at _____. I agree to waive my right to protection from termination for non-payment of this amount under D.P.U. 18123, Cromwell vs. Boston Gas Company, (November 1974).

I agree to pay \$ _____ arrearage as follows:

Fuel Assistance (or any other) commitment Amount: \$ _____

1. Amount paid by Customer: \$ _____, Date: _____
2. Payment of \$ _____ a month. First payment due _____
3. Payment of current bills at my new address as they come due.

I understand that the Bay State Gas Company agrees to initiate service in my name at

Street Address	City, State	Zip Code
----------------	-------------	----------

Customer signature	Date
--------------------	------

Employee #	Date	Time call recorded
------------	------	--------------------

Credit Department
Bay State Gas Company

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY-THIRD SET OF INFORMATION REQUESTS FROM ATTORNEY GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Danny G. Cote, General Manager
As to status of Discovery: Legal Counsel

AG-23-7 Please refer to the June 17, 2005, letter from the Company to the Attorney General regarding overdue discovery responses, Attachment B. Produce copies of this report for each month in 2004.

Response: Please see Attachment AG-23-7.

These materials were provided in response to a discovery conference and were not related to "overdue." discovery.

[BULK ATTACHMENT]

Program: wript031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

R E P O R T P A R A M E T E R S

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 01/01/2004
To Date : 01/31/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Bridgewater			Summer Street		1589986-1	LRMB	01/31/2004	Bare Steel 4 "	4 "	Fair	Exposed	Bare
85	Bridgewater			Summer Street		1589986-1	LRMB	01/31/2004	Coated Stl 1 1/2 "	1 1/2 "	Fair	Retired	Coal Tar
85	Bridgewater			Summer Street		1589986-1	LRMB	01/31/2004	Coated Stl 1 1/2 "	1 1/2 "	Like New/Good	New	Coal Tar
85	Brockton	117		Ames Street		5082931-1	LRMB	01/31/2004	Cast Iron 6 "	6 "	Fair	Exposed	Bare
85	Brockton	41		Clarendon Avenue		5082940-1	LRMB	01/31/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85	Brockton	247		Grove Street	Marty Langillier	5080809-1	LRMB	01/31/2004	Coated Stl 1 1/2 "	1 1/2 "	Like New/Good	Exposed	Epoxy
85	Brockton	241		Grove Street		5091698-1	LRMB	01/31/2004	Coated Stl 1 1/2 "	1 1/2 "	Fair	Exposed	Bare
85	Brockton	127		Hillcrest Avenue		5106856-1	LRMB	01/31/2004	Cast Iron 4 "	4 "	Fair	Exposed	Bare
85	Brockton	152		Montello Street N		5103285-1	LRMB	01/31/2004	Cast Iron 6 "	6 "	Fair	Exposed	Bare
85	Brockton	285		Plain Street		5081858-1	LRMB	01/31/2004	Plastic 1 1/4 "	1 1/4 "	Like New/Good	New	Bare
85	Brockton	285		Plain Street		5081858-1	LRMB	01/31/2004	Plastic 1 1/4 "	1 1/4 "	Fair	Exposed	Bare
85	Brockton	285		Plain Street		5081858-1	LRMB	01/31/2004	Plastic 1 1/4 "	1 1/4 "	Fair	Retired	Bare
85	Brockton	12		Stebbins Avenue		1548433-1	LRMB	01/31/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85	Brockton	556		W Elm Street		5083433-1	LRMB	01/31/2004	Cast Iron 4 "	4 "	Fair	Exposed	Bare
85	Brockton	200		Westgate Drive		5094602-1	LRMB	01/31/2004	Plastic 1 1/4 "	1 1/4 "	Like New/Good	New	Bare
85	Brockton	200		Westgate Drive		5094602-1	LRMB	01/31/2004	Plastic 1 1/4 "	1 1/4 "	Like New/Good	Exposed	Bare
85	East Bridgewater	379		N Bedford Street		5082203-1	LRMB	01/31/2004	Coated Stl 3/4 "	3/4 "	Like New/Good	Exposed	Coal Tar
85	East Bridgewater			Spear Avenue		5091548-1	LRMB	01/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	East Bridgewater	132		Union Street		4897207-1	LRMB	01/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	East Bridgewater	136		Washington Street		5082208-1	LRMB	01/31/2004	Coated Stl 3/4 "	3/4 "	Like New/Good	Exposed	Coal Tar
85	West Bridgewater	402		N Elm Street		5108325-1	LRMB	01/31/2004	Bare Steel 3 "	3 "	Very Poor	Exposed	Bare
85	West Bridgewater	188		S Main Street		5076547-1	LRMB	01/31/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85	West Bridgewater	188		S Main Street		5076550-1	LRMB	01/31/2004	Coated Stl 4 "	4 "	Like New/Good	Exposed	Coal Tar

Program: wwrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Franklin

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Foxboro			Cross Street		5107242-1	LRMB	01/31/2004	Coated Stl	2 "	Like New/Good	Exposed	Coal Tar
85	Foxboro	106		Main Street		5107093-1	LRMB	01/31/2004	Bare Steel	6 "	Poor	Exposed	Bare
85	Foxboro			North Street		5090117-1	LRMB	01/31/2004	Bare Steel	6 "	Poor	Exposed	Bare
85	Norfolk	9		Massachusetts Avenue		5076116-1	LRMB	01/31/2004	Coated Stl	2 "	Like New/Good	Exposed	Coal Tar
85	Walpole	204		East Street		5074960-1	LRMB	01/31/2004	Plastic	1/2 "	Fair	Exposed	Bare
85	Walpole	204		East Street		5074960-1	LRMB	01/31/2004	Plastic	1/2 "	Poor	Retired	Bare
85	Walpole	141		Washington Street		5082977-1	LRMB	01/31/2004	Coated Stl	2 "	Like New/Good	Exposed	Coal Tar

Program: wrprt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Duxbury	435		Bay Road		5098052-1	LRMVB	01/31/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85	Duxbury	435		Bay Road		5098052-1	LRMVB	01/31/2004	Bare Steel 2 "	2 "	Fair	Retired	Bare
85	Duxbury	435		Bay Road		5098052-1	LRMVB	01/31/2004	Plastic	2 "	Like New/Good	New	Bare
85	Duxbury	80		Crescent Street		5091249-1	LRMVB	01/31/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare
85	Duxbury	36		Indian Trail		5103294-1	LRMVB	01/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	Hanover	386		King Street		5106829-1	LRMVB	01/31/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
85	Hanson	968		W Washington Street		5103412-1	LRMVB	01/31/2004	Plastic	1 1/2 "	Fair	Exposed	Bare
85	Hanson	968		W Washington Street		5103412-1	LRMVB	01/31/2004	Coated Stl 3 3/4 "	3 3/4 "	Fair	Retired	Coal Tar
85	Hanson	968		W Washington Street		5103412-1	LRMVB	01/31/2004	Coated Stl 2 "	2 "	Like New/Good	New	Coal Tar
85	Marshfield	6		Chandler Drive		5082991-1	LRMVB	01/31/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85	Marshfield	99		Grandview Avenue		5066780-1	LRMVB	01/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Fair	Exposed	Bare
85	Marshfield	635		Plain Street		5097628-1	LRMVB	01/31/2004	Plastic	1 1/4 "	Like New/Good	Exposed	Bare
85	Marshfield	635		Plain Street		5097628-1	LRMVB	01/31/2004	Plastic	1 1/4 "	Like New/Good	Retired	Bare
85	Marshfield	635		Plain Street		5097628-1	LRMVB	01/31/2004	Plastic	1 1/4 "	Like New/Good	New	Bare
85	Marshfield	550		Summer Street		5097937-1	LRMVB	01/31/2004	Bare Steel 3 "	3 "	Very Poor	Exposed	Bare
85	Marshfield	111		Towne Way		5023231-1	LRMVB	01/31/2004	Coated Stl 3 3/4 "	3 3/4 "	Like New/Good	Exposed	Epoxy
85	Pembroke	73		Adams Avenue		5098990-1	LRMVB	01/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Very Poor	Exposed	Bare
85	Pembroke			Reservoir Road		5056038-1	LRMVB	01/31/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85	Pembroke			Union Street		5084510-1	LRMVB	01/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	Pembroke	8		Woodbine Avenue		5057108-1	LRMVB	01/31/2004	Bare Steel 1 "	1 "	Fair	Exposed	Bare
85	Scituate	204		Captain Pierce Road		5083085-1	LRMVB	01/31/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Randolph

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Avon	478		E Main Street		5093950-1	LRMXB	01/31/2004	Plastic	1/2 "	Fair	Exposed	Bare
85	Avon	478		E Main Street		5093950-1	LRMXB	01/31/2004	Plastic	1/2 "	Fair	Retired	Bare
85	Avon	478		E Main Street		5093950-1	LRMXB	01/31/2004	Plastic	1/2 "	Like New/Good	New	Bare
85	Holbrook	55		Union Street		5106863-1	LRMXB	01/31/2004	Bare Steel 6 "		Poor	Exposed	Bare
85	Randolph	389		Highland Avenue		4035347-1	LRMXB	01/31/2004	Bare Steel 2 "		Poor	Exposed	Bare
85	Stoughton	27		Birch Street		5040857-1	LRMXB	01/31/2004	Plastic	2 "	Like New/Good	Exposed	Bare
85	Stoughton	26		Kim Terrace		5075323-1	LRMXB	01/31/2004	Plastic	1/2 "	Like New/Good	Exposed	Bare
85	Stoughton	26		Kim Terrace		5075323-1	LRMXB	01/31/2004	Plastic	1/2 "	Like New/Good	Retired	Bare
85	Stoughton	152		Perry Street		5075323-1	LRMXB	01/31/2004	Plastic	1/2 "	Like New/Good	New	Bare
85	Stoughton	253		Pleasant Street		5088853-1	LRMXB	01/31/2004	Bare Steel 6 "		Fair	Exposed	Bare
85	Stoughton	304		Willow Street		5039342-1	LRMXB	01/31/2004	Bare Steel 4 "		Poor	Exposed	Bare
85	Stoughton	304		Willow Street		5093952-1	LRMXB	01/31/2004	Bare Steel 4 "		Poor	Exposed	Bare
85	Stoughton	304		Willow Street		5093952-1	LRMXB	01/31/2004	Bare Steel 2 "		Fair	Retired	Bare

Program: wrprt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Attleboro	668		Oak Hill Avenue		5076194-1	LRMXXB	01/31/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85	Attleboro	314		S Main Street		5082984-1	LRMXXB	01/31/2004	Plastic 8 "	8 "	Like New/Good	Exposed	Bare
85	Lakeville	80		Taunton Avenue		5090147-1	LRMXXB	01/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	Lakeville	47		Taunton Street		5090481-1	LRMXXB	01/31/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85	Mansfield	1006		West Street		5087200-1	LRMXXB	01/31/2004	Coated Stl 3/4 "	3/4 "	Like New/Good	New	Coal Tar
85	Mansfield	1006		West Street		5087200-1	LRMXXB	01/31/2004	Coated Stl 4 "	4 "	Like New/Good	Exposed	Coal Tar
85	Mansfield	1006		West Street		5087200-1	LRMXXB	01/31/2004	Coated Stl 3/4 "	3/4 "	Fair	Retired	Coal Tar
85	Raynham	300		New State Highway	SHAW'S	5083375-1	LRMXXB	01/31/2004	Coated Stl 1 1/4 "	1 1/4 "	Like New/Good	Exposed	Coal Tar
85	Taunton	14		Beacon Street		5087223-1	LRMXXB	01/31/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85	Taunton	84		Cedar Street		5105609-1	LRMXXB	01/31/2004	Cast Iron 4 "	4 "	Fair	Exposed	Bare
85	Taunton	55		Harrison Avenue		5084257-1	LRMXXB	01/31/2004	Cast Iron 3 "	3 "	Poor	Exposed	Bare
85	Taunton	8		Hoffman Street		5083008-1	LRMXXB	01/31/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85	Taunton	11		Laurel Street		5100780-1	LRMXXB	01/31/2004	Coated Stl 2 "	2 "	Like New/Good	Exposed	Coal Tar
85	Taunton	980		Middleboro Avenue		5090184-1	LRMXXB	01/31/2004	Wright Iron 6 "	6 "	Poor	Exposed	Bare
85	Taunton	385		Middleboro Avenue		5082967-1	LRMXXB	01/31/2004	Wright Iron 6 "	6 "	Poor	Exposed	Bare
85	Taunton	385		Middleboro Avenue		5082969-1	LRMXXB	01/31/2004	Wright Iron 6 "	6 "	Poor	Exposed	Bare
85	Taunton	179		Van Buren Street		5096610-1	LRMXXB	01/31/2004	Cast Iron 3 "	3 "	Fair	Exposed	Bare
85	Taunton	179		Van Buren Street		5096610-1	LRMXXB	01/31/2004	Bare Steel 3/4 "	3/4 "	Fair	Retired	Bare
85	Taunton	500		W Water		5082002-1	LRMXXB	01/31/2004	Coated Stl 8 "	8 "	Fair	Exposed	Coal Tar

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 83 Orders in this report.

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

REPORT PARAMETERS

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 02/01/2004
To Date : 02/29/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Bridgewater	6		Aldrich Road		5140784-1	LRMB	02/29/2004	Bare Steel	1 1/4 "	Fair	Exposed	Bare
85	Bridgewater	6		Aldrich Road		5140784-1	LRMB	02/29/2004	Bare Steel	1 "	Fair	Retired	Bare
85	Bridgewater	6		Aldrich Road		5140784-1	LRMB	02/29/2004	Plastic	1 1/4 "	Like New/Good	New	Bare
85	Brockton	22		Custer Street		5133566-1	LRMB	02/29/2004	Cast Iron	4 "	Fair	Exposed	Bare
85	Brockton			Green Street		5099225-1	LRMB	02/29/2004	Cast Iron	4 "	Fair	Exposed	Bare
85	Brockton	283		Grove Street		5108541-1	LRMB	02/29/2004	Coated Stl	1 1/2 "	Poor	Exposed	Coal Tar
85	Brockton			Lorraine Avenue		5099241-1	LRMB	02/29/2004	Coated Stl	2 "	Like New/Good	Exposed	Coal Tar
85	Brockton	56		Melrose Avenue		5131782-1	LRMB	02/29/2004	Coated Stl	2 "	Fair	Exposed	Coal Tar
85	Brockton	478		N Main Street		5133953-1	LRMB	02/29/2004	Plastic	2 "	Fair	Exposed	Bare
85	Brockton			Tremont Street		5083046-1	LRMB	02/29/2004	Cast Iron	4 "	Like New/Good	Exposed	Bare
85	Brockton	57		Vine Street		5147904-1	LRMB	02/29/2004	Cast Iron	6 "	Fair	Exposed	Bare
85	West Bridgewater	36		Plain Street		5141864-1	LRMB	02/29/2004	Bare Steel	6 "	Very Poor	Exposed	Bare
85	West Bridgewater	188		S Main Street		5141173-1	LRMB	02/29/2004	Bare Steel	4 "	Poor	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Franklin

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85 Foxboro	7		Basset Street		5158327-1	LRMB	02/29/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85 Foxboro	7		Basset Street		5110025-1	LRMB	02/29/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85 Franklin	75		Chestnut Street		5145473-1	LRMB	02/29/2004	Plastic 4 "	4 "	Like New/Good	New	Bare
85 Franklin	75		Chestnut Street		5145473-1	LRMB	02/29/2004	Bare Steel 3 "	3 "	Very Poor	Exposed	Bare
85 Franklin	75		Chestnut Street		5145473-1	LRMB	02/29/2004	Bare Steel 3 "	3 "	Very Poor	Retired	Bare
85 Franklin	643		E Central Street		5152634-1	LRMB	02/29/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85 Franklin	27		Highland Street		5111387-1	LRMB	02/29/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85 Franklin			Highland Street		5157682-1	LRMB	02/29/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85 Franklin	809		Lincoln Street		5109924-1	LRMB	02/29/2004	Bare Steel 6 "	6 "	Very Poor	Exposed	Bare
85 Franklin	47		Washington Street		5151132-1	LRMB	02/29/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85 Medway	23		Ellis Street		5083019-1	LRMB	02/29/2004	Coated Stl 2 "	2 "	Like New/Good	Exposed	Coal Tar
85 Walpole	54		Carpenter Road		5141268-1	LRMB	02/29/2004	Bare Steel 3/4 "	3/4 "	Fair	Exposed	Coal Tar
85 Walpole	19		Chandler Avenue		5150772-1	LRMB	02/29/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85 Walpole			Pine Street		5151146-1	LRMB	02/29/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85 Walpole	7		Rockwood Street		5103221-1	LRMB	02/29/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85 Wrentham	1783		Washington Street		5152663-1	LRMB	02/29/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85 Wrentham	147		Creek Street		5115675-1	LRMB	02/29/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare
85 Wrentham			South Street		5141232-1	LRMB	02/29/2004	Bare Steel 4 "	4 "	Very Poor	Exposed	Bare
85 Wrentham			South Street		5156440-1	LRMB	02/29/2004	Bare Steel 4 "	4 "	Fair	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contract Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Duxbury			White Street		5090238-1	LRMVB	02/29/2004	Bare Steel 1 1/2 "	1 1/2 "	Fair	Exposed	Bare
85	Duxbury	22		White Street		5098027-1	LRMVB	02/29/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85	Hanover	175		Myrtle Street		165977-1	LRMVB	02/29/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85	Hanover	756		Washington Street		5143099-1	LRMVB	02/29/2004	Plastic 1 1/4 "	1 1/4 "	Like New/Good	Exposed	Bare
85	Hanson	454		E Washington		5108354-1	LRMVB	02/29/2004	Bare Steel 8 "	8 "	Fair	Exposed	Bare
85	Hanson	122		W Washington Street		5144123-1	LRMVB	02/29/2004	Bare Steel 8 "	8 "	Poor	Exposed	Bare
85	Hanson			Wilkie Terrace		5149707-1	LRMVB	02/29/2004	Bare Steel 1 1/2 "	1 1/2 "	Very Poor	Exposed	Bare
85	Marshfield	7		Grasshopper Lane		5114463-1	LRMVB	02/29/2004	Coated Stl 1 1/4 "	1 1/4 "	Poor	Exposed	Coal Tar
85	Marshfield	1533		Main Street		5114463-1	LRMVB	02/29/2004	Plastic 2 "	2 "	Like New/Good	New	Bare
85	Marshfield	550		Summer Street		5154918-1	LRMVB	02/29/2004	Coated Stl 6 "	6 "	Fair	Exposed	Coal Tar
85	Marshfield			Wilson Road		5145474-1	LRMVB	02/29/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
85	Norwell	268		River Street		5107103-1	LRMVB	02/29/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85	Pembroke	55		Corporate Park		5107074-1	LRMVB	02/29/2004	Coated Stl 8 "	8 "	Fair	Exposed	Coal Tar
85	Pembroke	55		Corporate Park		5155135-1	LRMVB	02/29/2004	Plastic 4 "	4 "	Fair	Exposed	Bare
85	Pembroke	55		Corporate Park		5155135-1	LRMVB	02/29/2004	Plastic 4 "	4 "	Fair	Retired	Bare
85	Pembroke	32		Woodbine Avenue		5147729-1	LRMVB	02/29/2004	Plastic 4 "	4 "	Fair	New	Bare
85	Scituate	11		Collier Road		5150099-1	LRMVB	02/29/2004	Bare Steel 1 1/2 "	1 1/2 "	Poor	Exposed	Bare
									Coated Stl 2 "	2 "	Like New/Good	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
DISTRICT: Randolph

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85 Avon			Page Street		5082234-1	LRMB	02/29/2004	Plastic	2 "	Like New/Good	Exposed	Bare
85 Canton	444		York Street		5098005-1	LRMB	02/29/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Canton	504		York Street		5098011-1	LRMB	02/29/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Easton	11		Calvin Road		5122677-1	LRMB	02/29/2004	Coated Stl 2 "		Fair	Exposed	Coal Tar
85 Easton	131		Depot Street		1554616-1	LRMB	02/29/2004	Bare Steel 2 "		Fair	Exposed	Bare
85 Easton			Elm Street		5136538-1	LRMB	02/29/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Easton	10		Hayward Street		5145492-1	LRMB	02/29/2004	Bare Steel 1 1/4 "		Poor	Exposed	Coal Tar
85 Easton	28		Linden Street		5136534-1	LRMB	02/29/2004	Bare Steel 2 "		Poor	Exposed	Coal Tar
85 Easton	28		Linden Street		5136534-1	LRMB	02/29/2004	Coated Stl 3/4 "		Like New/Good	Retired	Coal Tar
85 Easton	5		Seaver Street		5136628-1	LRMB	02/29/2004	Coated Stl 2 "		Like New/Good	Exposed	Coal Tar
85 Easton	5		Seaver Street		5136628-1	LRMB	02/29/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Easton			Williams Street		5140766-1	LRMB	02/29/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Holbrook	2		Quincy Street		5107014-1	LRMB	02/29/2004	Bare Steel 1 1/2 "		Poor	Exposed	Bare
85 Holbrook	2		Quincy Street		5107014-1	LRMB	02/29/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Holbrook	2		Quincy Street		5107014-1	LRMB	02/29/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Holbrook	2		Quincy Street		5107014-1	LRMB	02/29/2004	Bare Steel 2 "		Very Poor	Retired	Bare
85 Holbrook	2		Quincy Street		5107014-1	LRMB	02/29/2004	Bare Steel 2 "		Very Poor	Retired	Bare
85 Holbrook	2		Quincy Street		5107014-1	LRMB	02/29/2004	Bare Steel 2 "		Very Poor	Retired	Bare
85 Holbrook	48		Quincy Street		5107045-1	LRMB	02/29/2004	Coated Stl 1 1/2 "		Very Poor	New	Coal Tar
85 Holbrook	48		Quincy Street		5107045-1	LRMB	02/29/2004	Bare Steel 1 "		Very Poor	Exposed	Bare
85 Holbrook	48		Quincy Street		5107045-1	LRMB	02/29/2004	Bare Steel 1 1/4 "		Very Poor	Exposed	Bare
85 Holbrook	48		Quincy Street		5107045-1	LRMB	02/29/2004	Bare Steel 1 1/2 "		Very Poor	Exposed	Bare
85 Holbrook	48		Quincy Street		5107045-1	LRMB	02/29/2004	Bare Steel 1 "		Very Poor	Retired	Bare
85 Holbrook	48		Quincy Street		5107045-1	LRMB	02/29/2004	Bare Steel 1 1/2 "		Very Poor	Retired	Bare
85 Holbrook	48		Quincy Street		5107045-1	LRMB	02/29/2004	Coated Stl 1 "		Like New/Good	New	Coal Tar
85 Holbrook	48		Quincy Street		5107045-1	LRMB	02/29/2004	Coated Stl 1 1/2 "		Like New/Good	New	Coal Tar
85 Holbrook	36		Wright Avenue		5153581-1	LRMB	02/29/2004	Bare Steel 1 1/4 "		Poor	Exposed	Bare
85 Sharon	45		Ames Street		5136539-1	LRMB	02/29/2004	Coated Stl 2 "		Poor	Exposed	Coal Tar
85 Sharon	81		Cottage Street		5097951-1	LRMB	02/29/2004	Bare Steel 2 "		Like New/Good	Exposed	Bare
85 Sharon			Deerfield Road		5127465-1	LRMB	02/29/2004	Coated Stl 3/4 "		Like New/Good	Exposed	Coal Tar
85 Sharon	15	17	Summer Street		5111245-1	LRMB	02/29/2004	Bare Steel 1 1/2 "		Poor	Exposed	Bare
85 Stoughton			Canton Street		192929-1	LRMB	02/29/2004	Bare Steel 6 "		Fair	Exposed	Bare
85 Stoughton	1943		Central Street		5097999-1	LRMB	02/29/2004	Bare Steel 3 "		Poor	Exposed	Bare
85 Stoughton	1508		Central Street		5115763-1	LRMB	02/29/2004	Plastic 1 1/2 "		Like New/Good	New	Bare
85 Stoughton	84		Chestnut Street		5087295-1	LRMB	02/29/2004	Bare Steel 1 1/4 "		Like New/Good	Exposed	Bare
85 Stoughton	22		Holbrook Avenue		5087300-1	LRMB	02/29/2004	Bare Steel 1 1/4 "		Poor	Exposed	Bare
85 Stoughton	185		Perry Street		5097968-1	LRMB	02/29/2004	Bare Steel 6 "		Poor	Exposed	Bare
85 Stoughton	32		Perry Street		5097982-1	LRMB	02/29/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Stoughton	337		Pleasant Street		5103236-1	LRMB	02/29/2004	Bare Steel 1 "		Very Poor	Exposed	Bare

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Attleboro	1290		County Street		5141127-1	LRMB	02/29/2004	Coated Stl 6	"	Fair	Exposed	Coal Tar
85	Attleboro	31		Emory Street		5111278-1	LRMB	02/29/2004	Wright Iron 3	"	Poor	Exposed	Bare
85	Attleboro	35		Emory Street		5126829-1	LRMB	02/29/2004	Wright Iron 3	"	Fair	Exposed	Bare
85	Attleboro	29		Emory Street		5127358-1	LRMB	02/29/2004	Wright Iron 3	"	Fair	Exposed	Bare
85	Attleboro	51		Emory Street		5127360-1	LRMB	02/29/2004	Wright Iron 6	"	Fair	Exposed	Bare
85	Attleboro	27		Emory Street		5143429-1	LRMB	02/29/2004	Wright Iron 3	"	Fair	Exposed	Bare
85	Attleboro	31		Emory Street		5145476-1	LRMB	02/29/2004	Cast Iron 4	"	Fair	Exposed	Bare
85	Attleboro	32		Holman Street		5150785-1	LRMB	02/29/2004	Bare Steel 4	"	Poor	Exposed	Bare
85	Attleboro	1205		Park Street		4888038-1	LRMB	02/29/2004	Bare Steel 4	"	Poor	Exposed	Bare
85	Attleboro	836		Park Street		5106884-1	LRMB	02/29/2004	Bare Steel 4	"	Very Poor	Exposed	Bare
85	Attleboro	220		S Main Street		5108409-1	LRMB	02/29/2004	Bare Steel 6	"	Poor	Exposed	Bare
85	Attleboro	26		Snell Street		5144143-1	LRMB	02/29/2004	Bare Steel 2	"	Poor	Exposed	Bare
85	Attleboro	183		Snell Street		5145503-1	LRMB	02/29/2004	Bare Steel 2	"	Like New/Good	Exposed	Epoxy
85	Attleboro	259		Snell Street		5145520-1	LRMB	02/29/2004	Bare Steel 3/4	"	Poor	Exposed	Epoxy
85	Mansfield	11		Spring Street		5145490-1	LRMB	02/29/2004	Bare Steel 2	"	Like New/Good	Retired	Bare
85	Mansfield	11		West Street		5141224-1	LRMB	02/29/2004	Bare Steel 2	"	Poor	Exposed	Bare
85	Norton	79		Mansfield Avenue		4261472-1	LRMB	02/29/2004	Bare Steel 6	"	Fair	Exposed	Bare
85	Seekonk	53		Pleasant Street		5144147-1	LRMB	02/29/2004	Bare Steel 8	"	Poor	Exposed	Bare
85	Seekonk	782		Bloomfield Street		5105648-1	LRMB	02/29/2004	Bare Steel 2	"	Very Poor	Exposed	Bare
85	Seekonk	214		Bloomfield Street		5105650-1	LRMB	02/29/2004	Bare Steel 2	"	Poor	Exposed	Bare
85	Seekonk	214		Cole Street		5140894-1	LRMB	02/29/2004	Bare Steel 2	"	Poor	Exposed	Bare
85	Seekonk	165		Cole Street		5140894-1	LRMB	02/29/2004	Stnlss Stl 3	"	Like New/Good	Exposed	Coal Tar
85	Seekonk	135		Newman Avenue		5140894-1	LRMB	02/29/2004	Stnlss Stl 3	"	Like New/Good	Exposed	Coal Tar
85	Seekonk	135		Warren Avenue		5144151-1	LRMB	02/29/2004	Bare Steel 4	"	Poor	Exposed	Bare
85	Seekonk	135		Warren Avenue		5148936-1	LRMB	02/29/2004	Plastic	2	Like New/Good	Exposed	Bare
85	Seekonk	135		Alfred Lord Boulevard		5144159-1	LRMB	02/29/2004	Bare Steel 2	"	Poor	Exposed	Bare
85	Taunton	371		Belmont Street		5108308-1	LRMB	02/29/2004	Cast Iron 4	"	Fair	Exposed	Bare
85	Taunton	385		Middleboro Avenue		5090170-1	LRMB	02/29/2004	Wright Iron 6	"	Fair	Exposed	Bare
85	Taunton	763		Middleboro Avenue		5158324-1	LRMB	02/29/2004	Bare Steel 6	"	Poor	Exposed	Bare
85	Taunton	763		Post Office Square		5127392-1	LRMB	02/29/2004	Bare Steel 6	"	Fair	Exposed	Bare
85	Taunton	763		Somerset Avenue		5107153-1	LRMB	02/29/2004	Cast Iron 4	"	Like New/Good	Exposed	Bare
85	Taunton	763		Somerset Avenue		5107153-1	LRMB	02/29/2004	Wright Iron 4	"	Fair	Exposed	Bare
85	Taunton	124		Somerset Avenue		5111082-1	LRMB	02/29/2004	Wright Iron 4	"	Poor	Retired	Bare
85	Taunton	49		Somerset Avenue		5144094-1	LRMB	02/29/2004	Cast Iron 3	"	Fair	Exposed	Bare
85	Taunton	415		W Britannia Street		5082971-1	LRMB	02/29/2004	Cast Iron 6	"	Like New/Good	Exposed	Bare
85	Taunton			Winthrop Street				02/29/2004	Coated Stl 3	"	Like New/Good	Exposed	Coal Tar

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 127 Orders in this report.

End of Report

Program: wwpt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

REPORT PARAMETERS

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 03/01/2004
To Date : 03/31/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
DISTRICT: Brockton

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85 Bridgewater			Park Avenue		5091671-1	LRMB	03/31/2004	Bare Steel 4 "	4 "	Fair	Exposed	Bare
85 Bridgewater			Park Avenue		5091671-1	LRMB	03/31/2004	Bare Steel 4 "	4 "	Very Poor	Retired	Bare
85 Bridgewater			Park Avenue		5091671-1	LRMB	03/31/2004	Plastic	4 "	Like New/Good	New	Bare
85 Bridgewater	31		Perkins Street		574171-1	LRMB	03/31/2004	Bare Steel 2 "	2 "	Like New/Good	Exposed	Coal Tar
85 Brockton	251		Ames Street		104765-1	LRMB	03/31/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85 Brockton	253		Ames Street		2037206-1	LRMB	03/31/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85 Brockton	178		Concord Street		5167409-1	LRMB	03/31/2004	Cast Iron 4 "	4 "	Poor	Exposed	Bare
85 Brockton	20		Custer Street		5154900-1	LRMB	03/31/2004	Cast Iron 4 "	4 "	Fair	Exposed	Bare
85 Brockton	17		First Street		5167795-1	LRMB	03/31/2004	Cast Iron 4 "	4 "	Fair	Exposed	Bare
85 Brockton	241		Grove Street		5181578-1	LRMB	03/31/2004	Coated Stl 1 1/2 "	1 1/2 "	Very Poor	Exposed	X Tru
85 Brockton	257		Pearl Street		5175307-1	LRMB	03/31/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85 Brockton	85		Tilton Avenue		1706000-1	LRMB	03/31/2004	Cast Iron 4 "	4 "	Fair	Exposed	Bare
85 Brockton	616		Torrey Street		5157300-1	LRMB	03/31/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85 Brockton	14		Weston Street		5159690-1	LRMB	03/31/2004	Cast Iron 4 "	4 "	Fair	Exposed	Bare
85 East Bridgewater			Spear Avenue		5175110-1	LRMB	03/31/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85 East Bridgewater	73		Summit Drive		5157442-1	LRMB	03/31/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85 East Bridgewater	144		Washington Street		5157385-1	LRMB	03/31/2004	Coated Stl 3/4 "	3/4 "	Like New/Good	Exposed	Coal Tar
85 West Bridgewater	10		Charles Street		5150754-1	LRMB	03/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85 West Bridgewater	188		S Main Street		5141181-1	LRMB	03/31/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wript031.p
Date: 06/23/2005
Req BY: Katherine Silver
DISTRICT: Franklin

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Bellingham	40		Puddingstone Lane		401096-1	LRMB	03/31/2004	Coated Stl 2	2 "	Fair	Exposed	Coal Tar
85	Foxboro	81		Carpenter Street		4061379-1	LRMB	03/31/2004	Bare Steel 6	6 "	Poor	Exposed	Bare
85	Foxboro	120		Main		5179285-1	LRMB	03/31/2004	Bare Steel 6	6 "	Very Poor	Exposed	Bare
85	Foxboro	231		Main Street		5162745-1	LRMB	03/31/2004	Bare Steel 6	6 "	Very Poor	Exposed	Bare
85	Foxboro	174		Main Street		5163831-1	LRMB	03/31/2004	Bare Steel 6	6 "	Fair	Exposed	Bare
85	Foxboro	231		Main Street		5169795-1	LRMB	03/31/2004	Bare Steel 6	6 "	Very Poor	Exposed	Bare
85	Foxboro	231		Main Street	Dave Giles	5171964-1	LRMB	03/31/2004	Bare Steel 6	6 "	Very Poor	Exposed	Bare
85	Foxboro	231		Main Street		5174315-1	LRMB	03/31/2004	Bare Steel 6	6 "	Poor	Exposed	Bare
85	Foxboro	122		Main Street		5175025-1	LRMB	03/31/2004	Bare Steel 6	6 "	Very Poor	Exposed	Bare
85	Foxboro	9		Main Street		5181460-1	LRMB	03/31/2004	Bare Steel 6	6 "	Poor	Exposed	Bare
85	Foxboro	136		Maple Place		5154768-1	LRMB	03/31/2004	Bare Steel 2	2 "	Poor	Exposed	Bare
85	Foxboro	4		Washington Street		5158329-1	LRMB	03/31/2004	Coated Stl 2	2 "	Fair	Exposed	Coal Tar
85	Franklin	27		Besso Street		5165655-1	LRMB	03/31/2004	Coated Stl 2	2 "	Like New/Good	Exposed	Coal Tar
85	Franklin	844		Highland Street		5175033-1	LRMB	03/31/2004	Bare Steel 6	6 "	Fair	Exposed	Bare
85	Medway	12		Lincoln Street		5154793-1	LRMB	03/31/2004	Bare Steel 2	2 "	Poor	Exposed	Bare
85	Medway	12		Brigham Street		5167412-1	LRMB	03/31/2004	Bare Steel 2	2 "	Poor	Exposed	Bare
85	Walpole	10		Main Street		5172153-1	LRMB	03/31/2004	Bare Steel 2	2 "	Poor	Exposed	Bare
85	Walpole	10		Riverside Place		5157316-1	LRMB	03/31/2004	Coated Stl 2	2 "	Like New/Good	Exposed	Epoxy
85	Walpole	10		Riverside Place		5176040-1	LRMB	03/31/2004	Bare Steel 2	2 "	Poor	Exposed	Bare
85	Walpole	10		Riverside Place		5187647-1	LRMB	03/31/2004	Bare Steel 2	2 "	Poor	Exposed	Bare

Program: wript031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85 Duxbury	567		Bay Road		510693-1	LRMB	03/31/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85 Duxbury	232		Crescent Street		4857620-1	LRMB	03/31/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85 Hanover	365		Circuit Street		5176005-1	LRMB	03/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85 Hanover			Webster Street		4096395-1	LRMB	03/31/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85 Hanson	700		High Street		5161814-1	LRMB	03/31/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85 Hanson	700		High Street		5161814-1	LRMB	03/31/2004	Bare Steel 4 "	4 "	Very Poor	Retired	Bare
85 Hanson	700		High Street		5161814-1	LRMB	03/31/2004	Bare Steel 4 "	4 "	Like New/Good	New	Epoxy
85 Hanson	122		W Washington Street		5171436-1	LRMB	03/31/2004	Bare Steel 8 "	8 "	Fair	Exposed	Bare
85 Hanson			Winter Street		5157348-1	LRMB	03/31/2004	Bare Steel 8 "	8 "	Fair	Exposed	Bare
85 Hanson			Winter Street		5176533-1	LRMB	03/31/2004	Bare Steel 8 "	8 "	Fair	Exposed	Bare
85 Marshfield	35		Main Street		1405147-1	LRMB	03/31/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
85 Marshfield	28		Main Street		5154898-1	LRMB	03/31/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
85 Marshfield	22		Main Street		5175199-1	LRMB	03/31/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
85 Marshfield	1245		S River Street		5154766-1	LRMB	03/31/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85 Marshfield	864		Summer Street		5154887-1	LRMB	03/31/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
85 Marshfield	864		Summer Street		5154887-1	LRMB	03/31/2004	Coated Stl 1 "	1 "	Very Poor	Retired	Coal Tar
85 Marshfield	864		Summer Street		5154887-1	LRMB	03/31/2004	Coated Stl 3/4 "	3/4 "	Like New/Good	New	Coal Tar
85 Pembroke	345		Washington Street		5160538-1	LRMB	03/31/2004	Coated Stl 4 "	4 "	Poor	Exposed	Coal Tar
85 Scituate	17		Greenfield Terrace		5164067-1	LRMB	03/31/2004	Coated Stl 1 1/2 "	1 1/2 "	Like New/Good	Exposed	Coal Tar
85 Scituate			Thomas Clapp Road		5174307-1	LRMB	03/31/2004	Coated Stl 2 "	2 "	Poor	Exposed	Coal Tar

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
DISTRICT: Randolph

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85 Canton	28		Hemlock Drive		5154926-1	LRMB	03/31/2004	Coated Stl 2 "		Fair	Exposed	Coal Tar
85 Canton	59		Independence Street		5179264-1	LRMB	03/31/2004	Bare Steel 1 1/4 "		Very Poor	Exposed	Bare
85 Easton	10		Hayward Street		5175095-1	LRMB	03/31/2004	Bare Steel 1 1/4 "		Poor	Exposed	Bare
85 Easton	5		Seaver Street		5163885-1	LRMB	03/31/2004	Bare Steel 2 "		Fair	Exposed	Bare
85 Easton	359		Washington Street		5136533-1	LRMB	03/31/2004	Bare Steel 4 "		Very Poor	Exposed	Bare
85 Easton	359		Washington Street		5136533-1	LRMB	03/31/2004	Plastic 1/2 "		Fair	Retired	Bare
85 Easton	359		Washington Street		5136533-1	LRMB	03/31/2004	Plastic 1/2 "		Like New/Good	New	Bare
85 Randolph	40		Maple Street		5154884-1	LRMB	03/31/2004	Bare Steel 2 "		Very Poor	Exposed	Bare
85 Sharon	15	17	Summer Street		5159710-1	LRMB	03/31/2004	Bare Steel 1 1/2 "		Poor	Exposed	Bare
85 Stoughton	36		Belmont Avenue	1890	5165707-1	LRMB	03/31/2004	Bare Steel 1 1/4 "		Poor	Exposed	Bare
85 Stoughton	37		Oakland		5175107-1	LRMB	03/31/2004	Plastic 2 "		Like New/Good	Exposed	Bare
85 Stoughton	37		Oakland		5175107-1	LRMB	03/31/2004	Plastic 2 "		Like New/Good	Retired	Bare
85 Stoughton			Park Street		5097990-1	LRMB	03/31/2004	Bare Steel 1 1/2 "		Very Poor	Exposed	Coal Tar
85 Stoughton			Pearl Street		5161822-1	LRMB	03/31/2004	Coated Stl 4 "		Like New/Good	Exposed	Bare
85 Stoughton	74		Pearl Street		5172148-1	LRMB	03/31/2004	Bare Steel 3 "		Poor	Exposed	Bare
85 Stoughton	74		Pearl Street		5172148-1	LRMB	03/31/2004	Plastic 1/2 "		Poor	Retired	Bare
85 Stoughton	74		Pearl Street		5172148-1	LRMB	03/31/2004	Plastic 1/2 "		Poor	New	Bare
85 Stoughton	184		Willow Street		5154923-1	LRMB	03/31/2004	Bare Steel 1 1/2 "		Very Poor	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wrpt031.p
Date: 06/23/2005
Reg By: Katherine Silver
DISTRICT: Taunton

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Attleboro			North Avenue		5159045-1	LRMB	03/31/2004	Bare Steel 6 "		Poor	Exposed	Bare
85	Attleboro	1201		Park Street		5169776-1	LRMB	03/31/2004	Bare Steel 4 "		Poor	Exposed	Bare
85	Attleboro	334		Robinson		5172159-1	LRMB	03/31/2004	Coated Stl 2 "		Like New/Good	New	Coal Tar
85	Attleboro	334		Robinson		5172159-1	LRMB	03/31/2004	Coated Stl 2 "		Fair	Exposed	Coal Tar
85	Attleboro	334		Robinson		5172159-1	LRMB	03/31/2004	Coated Stl 2 "		Very Poor	Retired	Coal Tar
85	Attleboro			Robinson Avenue		5131788-1	LRMB	03/31/2004	Bare Steel 3 "		Very Poor	Exposed	Bare
85	Attleboro	98		Scott Street		5171514-1	LRMB	03/31/2004	Bare Steel 2 "		Poor	Exposed	Bare
85	Attleboro	386		Thacher Street		5161591-1	LRMB	03/31/2004	Bare Steel 6 "		Poor	Exposed	Bare
85	Berkley			Berkley Street		5173431-1	LRMB	03/31/2004	Bare Steel 1 1/2 "		Poor	Exposed	Bare
85	Dighton	522		Main Street		5150782-1	LRMB	03/31/2004	Coated Stl 1 1/2 "		Like New/Good	New	Coal Tar
85	Dighton	504		Main Street		5150782-1	LRMB	03/31/2004	Wright Iron 1 1/2 "		Poor	Exposed	Bare
85	Dighton	504		Main Street		5150782-1	LRMB	03/31/2004	Wright Iron 1 1/2 "		Poor	Retired	Bare
85	Dighton			Somerset Avenue		5083033-1	LRMB	03/31/2004	Coated Stl 6 "		Like New/Good	Exposed	Coal Tar
85	Dighton	990		Somerset Avenue		5161677-1	LRMB	03/31/2004	Bare Steel 3 "		Very Poor	Exposed	Bare
85	Lakeville	80		Taunton Street		5171307-1	LRMB	03/31/2004	Stnless Stl 6 "		Like New/Good	Exposed	Bare
85	Mansfield	22		Kingman Avenue		5164021-1	LRMB	03/31/2004	Bare Steel 2 "		Poor	Exposed	Bare
85	Mansfield	22		Kingman Avenue		5172158-1	LRMB	03/31/2004	Bare Steel 2 "		Very Poor	Exposed	Bare
85	Mansfield	105		Union Street		5165437-1	LRMB	03/31/2004	Bare Steel 3 "		Poor	Exposed	Bare
85	Seekonk	31		Bloomfield Street		5175400-1	LRMB	03/31/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Seekonk	50		Lake Street		5177838-1	LRMB	03/31/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Seekonk	41		Lake Street		5177967-1	LRMB	03/31/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Taunton	3		Agawam Street		5087229-1	LRMB	03/31/2004	Plastic 2 "		Like New/Good	Exposed	Bare
85	Taunton	357		Bay Street		4927778-1	LRMB	03/31/2004	Cast Iron 6 "		Fair	Exposed	Bare
85	Taunton			Cullen Street		5171004-1	LRMB	03/31/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Taunton			Dana Street		5169830-1	LRMB	03/31/2004	Bare Steel 2 "		Very Poor	Exposed	Bare
85	Taunton			W Britannia Street		5157575-1	LRMB	03/31/2004	Cast Iron 6 "		Fair	Exposed	Bare

Continued on next page...

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 103 Orders in this report.

End of Report

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

R E P O R T P A R A M E T E R S

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 04/01/2004
To Date : 04/30/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Bridgewater	136		Broad Street		5563447-1	LRMXB	04/30/2004	Bare Steel	6 "	Poor	Exposed	Bare
85	Bridgewater	57		South Street		5175409-1	LRMXB	04/30/2004	Bare Steel	2 "	Poor	Exposed	Bare
85	West Bridgewater	485		Matfield Street		5196904-1	LRMXB	04/30/2004	Wrght Iron	4 "	Poor	Exposed	Bare
85	West Bridgewater	69		S Elm Street		5150767-1	LRMXB	04/30/2004	Bare Steel	2 "	Fair	Exposed	Bare

Continued on next page...

Program: wript031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Franklin

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85 Foxboro	81		Carpenter Street		5184933-1	LRMB	04/30/2004	Coated Stl 6 "		Like New/Good	Exposed	Coal Tar
85 Foxboro	144		Main Street		5199971-1	LRMB	04/30/2004	Bare Steel 6 "		Poor	Exposed	Bare
85 Foxboro	231		Main Street		5203929-1	LRMB	04/30/2004	Bare Steel 6 "		Fair	Exposed	Bare
85 Foxboro	191		Mechanic Street		5175310-1	LRMB	04/30/2004	Bare Steel 4 "		Poor	Exposed	Bare
85 Franklin	39		Daniels Street		5196145-1	LRMB	04/30/2004	Coated Stl 3 "		Fair	Exposed	Coal Tar
85 Franklin			Emmons Street		5149949-1	LRMB	04/30/2004	Coated Stl 4 "		Like New/Good	New	Coal Tar
85 Franklin			Emmons Street		5149949-1	LRMB	04/30/2004	Coated Stl 4 "		Like New/Good	Exposed	Coal Tar
85 Franklin			Emmons Street		5149949-1	LRMB	04/30/2004	Coated Stl 4 "		Like New/Good	Retired	Coal Tar
85 Franklin	864		Lincoln Street		5184623-1	LRMB	04/30/2004	Bare Steel 6 "		Poor	Exposed	Bare
85 Medway	12		Brigham Street		5202943-1	LRMB	04/30/2004	Bare Steel 2 "		Poor	Exposed	Bare

Program: wrprt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Marshfield	16		Summer Street		5563396-1	LRMB	04/30/2004	Plastic	1/2 "	Fair	Exposed	Bare
80	Marshfield	16		Summer Street		5563396-1	LRMB	04/30/2004	Plastic	1/2 "	Fair	Retired	Bare
80	Marshfield	16		Summer Street		5563396-1	LRMB	04/30/2004	Plastic	1/2 "	Like New/Good	New	Bare
85	Duxbury			Bayview Road		5140792-1	LRMB	04/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Duxbury			Bayview Road		5193671-1	LRMB	04/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Duxbury			Crescent Street		5210267-1	LRMB	04/30/2004	Bare Steel 3 "		Fair	Exposed	Bare
85	Duxbury			Landing Road		5161356-1	LRMB	04/30/2004	Coated Stl 1 1/2 "		Poor	Exposed	Coal Tar
85	Hanover			Franklin Road		5186695-1	LRMB	04/30/2004	Coated Stl 2 "		Fair	Exposed	Coal Tar
85	Hanson			Wilkie Terrace		5180581-1	LRMB	04/30/2004	Bare Steel 1 1/2 "		Very Poor	Exposed	Bare
85	Marshfield			Bruce Avenue		1670936-1	LRMB	04/30/2004	Bare Steel 1 1/2 "		Fair	Exposed	Bare
85	Marshfield			Ferry Street		5202626-1	LRMB	04/30/2004	Bare Steel 3 "		Poor	Exposed	Bare
85	Marshfield	201		Macker Terrace		5192637-1	LRMB	04/30/2004	Bare Steel 1 1/2 "		Fair	Exposed	Bare
85	Norwell	65		Dana Road		5197014-1	LRMB	04/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Norwell	49		High Street		5199813-1	LRMB	04/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Norwell	86		Main Street		5202629-1	LRMB	04/30/2004	Bare Steel 6 "		Poor	Exposed	Bare
85	Norwell	997		Main Street		5210307-1	LRMB	04/30/2004	Bare Steel 6 "		Fair	Exposed	Bare
85	Pembroke	138		Water Street		5208387-1	LRMB	04/30/2004	Bare Steel 4 "		Very Poor	Exposed	Bare
85	Pembroke	138		Water Street		5214865-1	LRMB	04/30/2004	Bare Steel 4 "		Fair	Exposed	Bare
85	Pembroke	138		Water Street		5214874-1	LRMB	04/30/2004	Bare Steel 4 "		Very Poor	Exposed	Bare
85	Scituate	533		Country Way		5202597-1	LRMB	04/30/2004	Bare Steel 3 "		Poor	Exposed	Bare
85	Scituate	11		Curtis Street		2072133-1	LRMB	04/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Scituate	30		Manchester Street		5198721-1	LRMB	04/30/2004	Bare Steel 1 1/2 "		Fair	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Randolph

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85 Canton	503		Chapman Street		4954753-1	LRMB	04/30/2004	Bare Steel	2 "	Fair	Exposed	Bare
85 Canton	33		Rockland Street		5205254-1	LRMB	04/30/2004	Bare Steel	1 1/2 "	Very Poor	Exposed	Bare
85 Canton	112		Spring Lane		5199822-1	LRMB	04/30/2004	Coated Stl	2 "	Fair	Exposed	Coal Tar
85 Canton	825		Washington Street		5183810-1	LRMB	04/30/2004	Bare Steel	3 "	Poor	Exposed	Bare
85 Randolph			Adelaide Street		5024450-1	LRMB	04/30/2004	Bare Steel	1 1/4 "	Very Poor	Exposed	Bare
85 Randolph			Adelaide Street		5024450-1	LRMB	04/30/2004	Bare Steel	1 1/4 "	Very Poor	Retired	Bare
85 Randolph			Adelaide Street		5024450-1	LRMB	04/30/2004	Coated Stl	1 1/4 "	Like New/Good	New	Coal Tar
85 Sharon	81		Cottage Street		5183853-1	LRMB	04/30/2004	Bare Steel	2 "	Poor	Exposed	Bare
85 Sharon	81		Cottage Street		5196872-1	LRMB	04/30/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
85 Stoughton	82		Chestnut Street		5159184-1	LRMB	04/30/2004	Bare Steel	1 1/4 "	Poor	Exposed	Bare
85 Stoughton	82		Chestnut Street		5159184-1	LRMB	04/30/2004	Bare Steel	1 1/4 "	Very Poor	Retired	Bare
85 Stoughton	82		Chestnut Street		5159184-1	LRMB	04/30/2004	Plastic	1 1/4 "	Like New/Good	New	Bare
85 Stoughton	13		Kenmore Road		5172019-1	LRMB	04/30/2004	Bare Steel	2 "	Poor	Exposed	Bare
85 Stoughton	74		Pearl Street		5175429-1	LRMB	04/30/2004	Bare Steel	3 "	Poor	Exposed	Bare
85 Stoughton	54		Perry Street		5175415-1	LRMB	04/30/2004	Bare Steel	2 "	Poor	Exposed	Bare

Program: wwrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
85	Attleboro	29		Emory Street		5206397-1	LRMB	04/30/2004	Cast Iron	3 "	Poor	Exposed	Bare
85	Attleboro			Marjorie Street		5190540-1	LRMB	04/30/2004	Plastic	1/2 "	Like New/Good	New	Bare
85	Attleboro			Marjorie Street		5190540-1	LRMB	04/30/2004	Coated Stl	3/4 "	Fair	Exposed	Epoxy
85	Attleboro			Marjorie Street		5190540-1	LRMB	04/30/2004	Coated Stl	3/4 "	Fair	Retired	Epoxy
85	Attleboro			Oakhill Avenue		5181624-1	LRMB	04/30/2004	Bare Steel	3 "	Poor	Exposed	Bare
85	Attleboro	220		S Main Street		5175301-1	LRMB	04/30/2004	Stnless Stl	6 "	Like New/Good	Exposed	Coal Tar
85	Attleboro	26		Snell Street		5157581-1	LRMB	04/30/2004	Bare Steel	2 "	Poor	Exposed	Bare
85	Seekonk	17	19	County Street		5208972-1	LRMB	04/30/2004	Bare Steel	2 "	Poor	Exposed	Bare
85	Seekonk	364		Newman Avenue		5198699-1	LRMB	04/30/2004	Bare Steel	4 "	Fair	Exposed	Bare
85	Taunton	93		Fisher Street		5184626-1	LRMB	04/30/2004	Bare Steel	8 "	Fair	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 61 Orders in this report.

End of Report

Program: wwprt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

R E P O R T P A R A M E T E R S

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 05/01/2004
To Date : 05/31/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Bridgewater	32		Leonard Street		5574995-1	LRMVB	05/13/2004	Plastic	1/2 "		New	Bare
80	Bridgewater	32		Leonard Street		5574995-1	LRMVB	05/13/2004	Bare Steel 2 "		Fair	Exposed	Bare
80	Bridgewater	32		Leonard Street		5574995-1	LRMVB	05/13/2004	Plastic	1/2 "	Fair	Retired	
80	Brockton	35		Cary Street		5576028-1	LRMVB	05/14/2004	Cast Iron 8 "		Fair	Exposed	Bare
80	Brockton	35		Cary Street		5576028-1	LRMVB	05/14/2004	Bare Steel 6 "		Fair	Exposed	Bare
80	Brockton			W Chestnut Street		5576146-1	LRMVB	05/14/2004	Bare Steel 6 "		Fair	Exposed	Bare
80	East Bridgewater	100		Bedford Street		421763-1	LRMVB	05/24/2004	Bare Steel 6 "		Poor	Exposed	Bare
80	West Bridgewater	458		Matfield Street		5539155-1	LRMVB	05/18/2004	Wright Iron 4 "		Poor	Exposed	Bare
80	West Bridgewater	448		Matfield Street		5554038-1	LRMVB	05/25/2004	Bare Steel 4 "		Poor	Exposed	Bare
85	Brockton	135		Summer Street		5235373-1	LRMVB	05/31/2004	Coated Stl 2 "		Like New/Good	Exposed	Coal Tar
85	East Bridgewater	47		Cook Street		5224738-1	LRMVB	05/31/2004	Bare Steel 3 "		Fair	Exposed	Bare
85	East Bridgewater			Cook Street		5225430-1	LRMVB	05/31/2004	Bare Steel 3 "		Fair	Exposed	Bare

Program: wrpt031.P
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Franklin

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
20 Foxboro	114		Main Street		5567855-1	LRMX	05/06/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
80 Foxboro	116		Main Street		5563379-1	LRMXB	05/01/2004	Bare Steel 6 "	6 "	Very Poor	Exposed	Bare
80 Foxboro	114		Main Street		5574999-1	LRMXB	05/14/2004	Bare Steel 6 "	6 "	Very Poor	Exposed	Bare
80 Medway	101		Maple Lane		5573857-1	LRMXB	05/12/2004	Bare Steel 3 "	3 "	Very Poor	Exposed	Bare
80 Medway	3		Oakland Street		5578586-1	LRMXB	05/26/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
85 Foxboro	29		Hayden Drive		5206567-1	LRMXB	05/31/2004	Plastic 2 "	2 "	Like New/Good	Exposed	Bare
85 Foxboro	29		Hayden Drive		5206567-1	LRMXB	05/31/2004	Plastic 2 "	2 "	Like New/Good	Retired	Bare
85 Foxboro	231		Main Street		5211419-1	LRMXB	05/31/2004	Bare Steel 6 "	6 "	Very Poor	Exposed	Bare
85 Foxboro	231		Main Street		5215822-1	LRMXB	05/31/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85 Foxboro	231		Main Street		5228328-1	LRMXB	05/31/2004	Bare Steel 6 "	6 "	Very Poor	Exposed	Bare
85 Franklin			Main Street		5202882-1	LRMXB	05/31/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85 Franklin	164		Main Street		5233851-1	LRMXB	05/31/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85 Franklin	164		Main Street		5236415-1	LRMXB	05/31/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85 Medway	12		Brigham Street		5215437-1	LRMXB	05/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85 Medway	101		Maple Lane		5223306-1	LRMXB	05/31/2004	Bare Steel 3 "	3 "	Very Poor	Exposed	Bare
85 Medway	101		Maple Lane		5225592-1	LRMXB	05/31/2004	Coated Stl 3/4 "	3/4 "	Like New/Good	Exposed	Coal Tar
85 Walpole	5		Oakland Street		4777234-1	LRMXB	05/31/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare
85 Walpole	36		Ellis Street		5214243-1	LRMXB	05/31/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85 Walpole	20	22	Rhoades Avenue		5331769-1	LRMXB	05/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85 Walpole	18		Riverside Place		5211436-1	LRMXB	05/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Duxbury	134		Bay Road		5503498-1	LRMBX	05/25/2004	Bare Steel	1 1/2 "	Fair	Exposed	Bare
80	Duxbury	52		Bayview Road		5503491-1	LRMBX	05/05/2004	Bare Steel	2 "	Poor	Exposed	Bare
80	Hanover	195		Washington Street		5576092-1	LRMBX	05/13/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
80	Hanson	39		Park Street		5581732-1	LRMBX	05/20/2004	Bare Steel	1 1/2 "	Very Poor	Exposed	Bare
80	Marshfield	30		9th Road		5570873-1	LRMBX	05/08/2004	Bare Steel	1 1/2 "	Fair	Exposed	Bare
80	Norwell	36		Franklin Road		5569974-1	LRMBX	05/07/2004	Plastic	1 1/2 "	New	New	Bare
80	Norwell	36		Franklin Road		5569974-1	LRMBX	05/07/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
80	Norwell	36		Franklin Road		5569974-1	LRMBX	05/07/2004	Plastic	1 1/2 "	Fair	Retired	Bare
80	Norwell	86		High Street		5558950-1	LRMBX	05/12/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
80	Norwell	86		High Street		5580624-1	LRMBX	05/21/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
80	Norwell	8		Wilger Road		5572623-1	LRMBX	05/11/2004	Bare Steel	3 "	Fair	Exposed	Bare
80	Scituate	187		Gannett Road		5588515-1	LRMBX	05/27/2004	Bare Steel	1 "	Fair	Exposed	Bare
80	Scituate	187		Stockbridge Road		5588515-1	LRMBX	05/27/2004	Bare Steel	1 "	Fair	Retired	Bare
85	Duxbury	435		Stockbridge Road		5175104-1	LRMBX	05/31/2004	Bare Steel	2 "	Fair	Exposed	Bare
85	Duxbury	282		Bay Road		5111255-1	LRMBX	05/31/2004	Coated Stl	6 "	Fair	Exposed	Coal Tar
85	Duxbury	178		Congress Street		5206513-1	LRMBX	05/31/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
85	Duxbury	18		King Caesar Road		5237949-1	LRMBX	05/31/2004	Bare Steel	2 "	Poor	Exposed	Bare
85	Duxbury	18		Marshall Street		5175090-1	LRMBX	05/31/2004	Bare Steel	1 1/2 "	Poor	Exposed	Bare
85	Duxbury	154		Mullins Avenue		5214911-1	LRMBX	05/31/2004	Bare Steel	1 1/2 "	Poor	Exposed	Bare
85	Hanson	556		Mullins Avenue		5183801-1	LRMBX	05/31/2004	Coated Stl	6 "	Fair	Exposed	Coal Tar
85	Marshfield	272		Woodland Drive		5222930-1	LRMBX	05/31/2004	Bare Steel	3 "	Poor	Exposed	Bare
85	Marshfield	1308		Maquan Street		5220968-1	LRMBX	05/31/2004	Bare Steel	3 "	Very Poor	Exposed	Bare
85	Marshfield	132		Deerhill Lane		5192911-1	LRMBX	05/31/2004	Bare Steel	3 "	Fair	Exposed	Bare
85	Marshfield	80		Ferry Street		5231474-1	LRMBX	05/31/2004	Bare Steel	1 1/2 "	Poor	Exposed	Bare
85	Marshfield	80		Ocean Street		5217021-1	LRMBX	05/31/2004	Bare Steel	1 1/4 "	Fair	Exposed	Coal Tar
85	Marshfield	80		Stratton Avenue		5216920-1	LRMBX	05/31/2004	Coated Stl	2 "	Very Poor	Exposed	Bare
85	Norwell	80		Central Street		5199809-1	LRMBX	05/31/2004	Bare Steel	2 "	Fair	Exposed	Bare
85	Norwell	80		High Street		5220913-1	LRMBX	05/31/2004	Bare Steel	2 "	Fair	Exposed	Bare
85	Norwell	80		Jacobs Trail		5220913-1	LRMBX	05/31/2004	Coated Stl	2 "	Fair	Exposed	Coal Tar
85	Norwell	80		Jacobs Trail		5220913-1	LRMBX	05/31/2004	Coated Stl	2 "	Fair	Retired	Coal Tar
85	Norwell	80		Jacobs Trail		4897312-1	LRMBX	05/31/2004	Coated Stl	2 "	Like New/Good	New	Epoxy
85	Pembroke	8		Alma Avenue		5217169-1	LRMBX	05/31/2004	Bare Steel	1 1/2 "	Fair	Exposed	Bare
85	Pembroke	33		Beechwood Avenue		5217169-1	LRMBX	05/31/2004	Coated Stl	2 "	Fair	Exposed	Coal Tar

Program: wrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Randolph

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Canton	120		Tolman Street		555208-1	LRMB	05/19/2004	Plastic	2 "		New	Bare
80 Canton	120		Tolman Street		555208-1	LRMB	05/19/2004	Bare Steel 1 1/2 "		Poor	Exposed	Bare
80 Canton	120		Tolman Street		555208-1	LRMB	05/19/2004	Bare Steel 1 1/2 "		Very Poor	Retired	Bare
80 Canton	700		Washington Street		5553975-1	LRMB	05/01/2004	Bare Steel 4 "		Poor	Exposed	Bare
80 Canton	626		Washington Street		578563-1	LRMB	05/15/2004	Bare Steel 4 "		Poor	Exposed	Bare
80 Easton	125		Center Street		5554046-1	LRMB	05/28/2004	Bare Steel 2 "		Poor	Exposed	Bare
80 Sharon			Oakhill Drive		5554053-1	LRMB	05/25/2004	Coated Stl 2 "		Like New/Good	Exposed	Coal Tar
80 Stoughton	32		Pearl Street		5577647-1	LRMB	05/15/2004	Bare Steel 3 "		Poor	Exposed	Bare
85 Canton	555		York Street		5206525-1	LRMB	05/31/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Easton	10		Hayward Street		5277694-1	LRMB	05/31/2004	Bare Steel 1 1/4 "		Poor	Exposed	Bare
85 Easton	12		Hayward Street		5277699-1	LRMB	05/31/2004	Bare Steel 1 1/4 "		Very Poor	Exposed	Bare
85 Easton			Rockland Street		5212546-1	LRMB	05/31/2004	Coated Stl 2 "		Like New/Good	Exposed	Epoxy
85 Easton			Turnpike Street		5212747-1	LRMB	05/31/2004	Bare Steel 2 "		Fair	Exposed	Bare
85 Holbrook	6		Manor Road		5150171-1	LRMB	05/31/2004	Bare Steel 1 1/2 "		Fair	Exposed	Bare
85 Holbrook	281		S Franklin Street		5226592-1	LRMB	05/31/2004	Bare Steel 6 "		Poor	Exposed	Bare
85 Sharon	335		N Main Street		5220977-1	LRMB	05/31/2004	Bare Steel 3 "		Very Poor	Exposed	Bare
85 Stoughton	78		Brock Street		5233426-1	LRMB	05/31/2004	Bare Steel 6 "		Poor	Exposed	Bare

Program: wrprt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Attleboro	85		Adamsdale Avenue		5581781-1	LRMXB	05/21/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
80	Attleboro	200		N Main Street		5516270-1	LRMXB	05/23/2004	Cast Iron 6 "	6 "	Fair	Exposed	Bare
80	Attleboro	86		Wilmarth Street		5578376-1	LRMXB	05/18/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
80	Norton	153		W Main Street		5552193-1	LRMXB	05/03/2004	Bare Steel 6 "	6 "	Very Poor	Exposed	Bare
80	Norton	97		W Main Street		5104433-1	LRMXB	05/06/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85	Attleboro	32		Biltmore Street		5216799-1	LRMXB	05/31/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85	Attleboro	114		Lucy Drive		5235255-1	LRMXB	05/31/2004	Coated Stl 3/4 "	3/4 "	Fair	Exposed	Coal Tar
85	Berkley	519		Berkley Street		5087236-1	LRMXB	05/31/2004	Plastic 2 "	2 "	Like New/Good	Exposed	Bare
85	Lakeville			Taunton Avenue		5216698-1	LRMXB	05/31/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85	Mansfield	96		Union Street		5216828-1	LRMXB	05/31/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
85	Mansfield			West Street		5201014-1	LRMXB	05/31/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85	Mansfield	381		Willow Street		5214627-1	LRMXB	05/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	Norton			S Worcester Street		5175066-1	LRMXB	05/31/2004	Bare Steel 8 "	8 "	Fair	Exposed	Bare
85	Seekonk			Central Avenue		5233885-1	LRMXB	05/31/2004	Bare Steel 3 "	3 "	Very Poor	Exposed	Bare

Continued on next page...

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 95 Orders in this report.

End of Report

Program: wrprt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

R E P O R T P A R A M E T E R S

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 06/01/2004
To Date : 06/30/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Bridgewater			High Street		4028937-1	LRMXB	06/27/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80	Bridgewater	111		Mount Prospect Street		5577439-1	LRMXB	06/07/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80	Bridgewater	25		Robin Road		5578603-1	LRMXB	06/17/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
80	Brockton	555		Center Street		5580538-1	LRMXB	06/05/2004	Cast Iron 8 "	8 "	Fair	Exposed	Bare
80	West Bridgewater			N Elm Street		1907649-1	LRMXB	06/02/2004	Bare Steel 3/4 "	3/4 "	Very Poor	Exposed	Bare
80	West Bridgewater	192		S Main Street	Moe Fellming	5590383-1	LRMXB	06/01/2004	Bare Steel 4 "	4 "	Very Poor	Exposed	Bare
85	Brockton			N Warren Avenue		5223170-1	LRMXB	06/30/2004	Cast Iron 4 "	4 "	Fair	Exposed	Bare
85	Brockton			White Avenue		373940-1	LRMXB	06/30/2004	Cast Iron 8 "	8 "	Fair	Exposed	Bare

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Franklin

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Franklin	9		Washington Street		5594371-1	LRMVB	06/03/2004	Coated Stl	3/4 "	Fair	Exposed	Coal Tar
80	Medway			Brigham Street		5577432-1	LRMVB	06/22/2004	Bare Steel	2 "	Fair	Exposed	Bare
80	Medway	8		Phillips Street		5225462-1	LRMVB	06/17/2004	Bare Steel	2 "	Poor	Exposed	Bare
80	Medway			Wellington Street		4144875-1	LRMVB	06/03/2004	Bare Steel	3 "	Poor	Exposed	Bare
80	Medway	30		Wellington Street		5577413-1	LRMVB	06/02/2004	Bare Steel	3 "	Fair	Exposed	Bare
80	Walpole	103		Common Street		5601952-1	LRMVB	06/23/2004	Bare Steel	2 "	Fair	Exposed	Bare
85	Bellingham	166		Hartford Avenue		5260381-1	LRMVB	06/30/2004	Coated Stl	4 "	Poor	Exposed	Coal Tar
85	Franklin	3		Dawn Marie Circle		5223174-1	LRMVB	06/30/2004	Plastic	2 "	Like New/Good	Exposed	Bare
85	Franklin	113		Dean Avenue		5260374-1	LRMVB	06/30/2004	Bare Steel	3 "	Fair	Exposed	Bare
85	Franklin	609		Lincoln Street		5216819-1	LRMVB	06/30/2004	Bare Steel	6 "	Very Poor	Exposed	Bare
85	Franklin	22		Woodhaven Drive		5228313-1	LRMVB	06/30/2004	Plastic	2 "	Like New/Good	Exposed	Bare
85	Medway			Oakland Street		5228302-1	LRMVB	06/30/2004	Bare Steel	3 "	Poor	Exposed	Bare
85	Walpole	52		Federal Street		5244969-1	LRMVB	06/30/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
85	Walpole	10		Macdonald Circle		5230490-1	LRMVB	06/30/2004	Coated Stl	2 "	Like New/Good	Exposed	Coal Tar
85	Walpole	14		Maple Street		5236379-1	LRMVB	06/30/2004	Bare Steel	2 "	Poor	Exposed	Bare
85	Walpole	29		Page Avenue		5244970-1	LRMVB	06/30/2004	Bare Steel	2 "	Fair	Exposed	Bare
85	Walpole	3		Windsor Road		4042930-1	LRMVB	06/30/2004	Plastic	1 "	Like New/Good	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
DISTRICT: Hanover

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Hanson	334		High Street		5605508-1	LRMxB	06/27/2004	Coated Stl 4 "	"	Poor	Exposed	Coal Tar
80	Hanson	38		Park Street		5583690-1	LRMxB	06/02/2004	Bare Steel 1 1/2 "	"	Fair	Exposed	Bare
80	Hanson	52		Pierce Avenue		5605513-1	LRMxB	06/25/2004	Bare Steel 1 1/2 "	"	Fair	Exposed	Bare
80	Marshfield	24		Anderson Drive		5431958-1	LRMxB	06/18/2004	Coated Stl 2 "	"	Fair	Exposed	Coal Tar
80	Marshfield	12		Foster Avenue		5603067-1	LRMxB	06/14/2004	Plastic 2 "	"	Like New/Good	Exposed	Bare
80	Marshfield	12		Shawmut Avenue		5603190-1	LRMxB	06/22/2004	Bare Steel 1 1/2 "	"	Fair	Exposed	Bare
80	Marshfield	23		Summer Street		5558758-1	LRMxB	06/02/2004	Bare Steel 3 "	"	Very Poor	Exposed	Bare
80	Norwell	41		Dana Road		5593255-1	LRMxB	06/04/2004	Bare Steel 2 "	"	Very Poor	Exposed	Bare
80	Norwell	47		Wildier Road		5584709-1	LRMxB	06/03/2004	Bare Steel 2 "	"	Very Poor	Exposed	Bare
80	Pembroke	13		School Street		5580552-1	LRMxB	06/05/2004	Bare Steel 2 "	"	Very Poor	Exposed	Bare
80	Scituate	17		Eleventh Avenue		5588502-1	LRMxB	06/08/2004	Coated Stl 1 1/2 "	"	Very Poor	Exposed	Coal Tar
80	Scituate	26		Jenkins Place		5599528-1	LRMxB	06/21/2004	Coated Stl 2 "	"	Fair	Exposed	Coal Tar
85	Duxbury	34		Mayflower Lane		5248583-1	LRMxB	06/30/2004	Bare Steel 1 1/4 "	"	Like New/Good	Exposed	Bare
85	Duxbury	42		Sunset Road		5261725-1	LRMxB	06/30/2004	Bare Steel 1 1/2 "	"	Very Poor	Exposed	Bare
85	Hanover	375		Circuit Street		1275629-1	LRMxB	06/30/2004	Bare Steel 2 "	"	Like New/Good	Exposed	Bare
85	Hanover	347		Circuit Street		5172009-1	LRMxB	06/30/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
85	Hanover	401		Circuit Street		5246651-1	LRMxB	06/30/2004	Bare Steel 2 "	"	Like New/Good	Exposed	Bare
85	Hanson	1		Maquan Street		5231463-1	LRMxB	06/30/2004	Bare Steel 4 "	"	Fair	Exposed	Bare
85	Marshfield	14		Satucket Avenue		5237965-1	LRMxB	06/30/2004	Bare Steel 1 1/2 "	"	Fair	Exposed	Bare
85	Norwell	997		Main Street		5208521-1	LRMxB	06/30/2004	Bare Steel 6 "	"	Like New/Good	Exposed	Bare
85	Pembroke	39		Woodbine Avenue		5211917-1	LRMxB	06/30/2004	Bare Steel 1 1/2 "	"	Fair	Exposed	Bare
85	Scituate	169		Bull Rush Farm Road		5259466-1	LRMxB	06/30/2004	Bare Steel 1 1/2 "	"	Fair	Exposed	Bare

Program: wrprt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Randolph

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Avon			Gill Street		5565232-1	LRMVB	06/08/2004	Bare Steel 2 "		Poor	Exposed	Bare
80 Canton	632		Washington Street		5597154-1	LRMVB	06/06/2004	Bare Steel 4 "		Very Poor	Exposed	Bare
80 Easton			Baldwin Street		5610529-1	LRMVB	06/23/2004	Bare Steel 2 "		Very Poor	Exposed	Bare
80 Easton			Washington Street		5543615-1	LRMVB	06/02/2004	Bare Steel 4 "		Fair	Exposed	Bare
80 Easton			Washington Street		5543615-1	LRMVB	06/02/2004	Bare Steel 2 "		Fair	Exposed	Bare
80 Easton			Washington Street		5594293-1	LRMVB	06/02/2004	Bare Steel 4 "		Fair	Exposed	Bare
80 Holbrook	3		Spring Street		5598007-1	LRMVB	06/09/2004	Bare Steel 6 "		Very Poor	Exposed	Bare
80 Holbrook	3		Spring Street		5600449-1	LRMVB	06/11/2004	Bare Steel 6 "		Fair	Exposed	Bare
80 Holbrook	3		Spring Street		5607534-1	LRMVB	06/19/2004	Bare Steel 6 "		Very Poor	Exposed	Bare
80 Randolph	27		Ely Street		5612853-1	LRMVB	06/24/2004	Bare Steel 1 1/4 "		Very Poor	Exposed	Bare
80 Randolph	47		Fitch Terrace		5615641-1	LRMVB	06/28/2004	Coated Stl 2 "		Fair	Exposed	Coal Tar
80 Randolph	11		Maple Circle		5603127-1	LRMVB	06/18/2004	Bare Steel 1 1/2 "		Poor	Exposed	Bare
80 Randolph	1144		N Harriette Street		5552152-1	LRMVB	06/01/2004	Bare Steel 1 1/4 "		Poor	Exposed	Bare
80 Stoughton	1144		Central Street		5606719-1	LRMVB	06/19/2004	Bare Steel 4 "		Very Poor	Exposed	Bare
80 Stoughton	1144		Central Street		5608309-1	LRMVB	06/19/2004	Bare Steel 4 "		Very Poor	Exposed	Bare
85 Easton			Seaver Street		4906196-1	LRMVB	06/30/2004	Bare Steel 1 1/4 "		Very Poor	Exposed	Bare
85 Easton	43		Sheridan Street		5253719-1	LRMVB	06/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85 Holbrook	6		Spring Street		5245010-1	LRMVB	06/30/2004	Bare Steel 6 "		Like New/Good	Exposed	Bare
85 Randolph	12		McColgan Drive		5244959-1	LRMVB	06/30/2004	Plastic 2 "		Like New/Good	Exposed	Bare
85 Randolph	8		S Harriette Street		5257810-1	LRMVB	06/30/2004	Bare Steel 1 1/4 "		Fair	Exposed	Bare
85 Randolph	24		Webster Street		5265249-1	LRMVB	06/30/2004	Bare Steel 2 "		Very Poor	Exposed	Bare
85 Randolph	24		Webster Street		5265249-1	LRMVB	06/30/2004	Bare Steel 1 "		Very Poor	Retired	Bare
85 Sharon	73		Billings Street		5211927-1	LRMVB	06/30/2004	Bare Steel 1 1/4 "		Fair	Exposed	Bare
85 Stoughton	78		Brock Street		5242002-1	LRMVB	06/30/2004	Bare Steel 6 "		Poor	Exposed	Bare

Program: wrprt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Mansfield	1000		West Street		5317287-1	LRMXB	06/07/2004	Coated Stl 4 "	4 "	Fair	Exposed	Epoxy
80	Mansfield	395		Willow Street		5584674-1	LRMXB	06/05/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
80	Taunton	427		Winthrop Street		5590413-1	LRMXB	06/08/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85	Attleboro	310		Bishop Street		5250043-1	LRMXB	06/30/2004	Plastic	1/2 "	Like New/Good	New	Bare
85	Attleboro	310		Bishop Street		5250043-1	LRMXB	06/30/2004	Coated Stl 4 "	4 "	Fair	Exposed	Coal Tar
85	Attleboro	310		Bishop Street		5250043-1	LRMXB	06/30/2004	Plastic	1/2 "	Fair	Retired	Bare
85	Attleboro	384		South Avenue		5253691-1	LRMXB	06/30/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85	Norton	809		Washington Street		5253822-1	LRMXB	06/30/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85	Seekonk	111		S Worcester Street		5228307-1	LRMXB	06/30/2004	Bare Steel 8 "	8 "	Poor	Exposed	Bare
85	Seekonk	45		Bloomfield Street		5241290-1	LRMXB	06/30/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	Seekonk	184		County Street		5216841-1	LRMXB	06/30/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	Seekonk			Newman Avenue		5255000-1	LRMXB	06/30/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85	Taunton			Winthrop Street		5234938-1	LRMXB	06/30/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	Taunton	427		Winthrop Street		5252916-1	LRMXB	06/30/2004	Bare Steel 2 "	2 "	Like New/Good	Exposed	Bare

Continued on next page...

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 86 Orders in this report.

End of Report

Program: wwpt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

REPORT PARAMETERS

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 07/01/2004
To Date : 07/31/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Bridgewater	84		Auburn Street		5593242-1	LRMVB	07/17/2004	Bare Steel	1 1/2 "	Very Poor	Exposed	Bare
80	Bridgewater			Broad Street		5510554-1	LRMVB	07/06/2004	Bare Steel	4 "	Poor	Exposed	Bare
80	Bridgewater	355		Laurel Street		5638856-1	LRMVB	07/23/2004	Coated Stl	4 "	Fair	Exposed	Coal Tar
80	Bridgewater	355		Laurel Street		5638856-1	LRMVB	07/23/2004	Plastic	1/2 "	Fair	Retired	Bare
80	Bridgewater	355		Laurel Street		5638856-1	LRMVB	07/23/2004	Plastic	1/2 "	Like New/Good	New	Bare
80	Bridgewater	47		Lawrence Avenue		5565253-1	LRMVB	07/15/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
80	Brockton	85		Cary Street		5621390-1	LRMVB	07/05/2004	Bare Steel	6 "	Very Poor	Exposed	Bare
80	Brockton	52		Edgar Street		5610377-1	LRMVB	07/19/2004	Bare Steel	2 "	Poor	Exposed	Bare
80	Brockton	671		Plain		5633373-1	LRMVB	07/26/2004	Bare Steel	6 "	Very Poor	Exposed	Bare
80	Brockton	671		Plain		5640733-1	LRMVB	07/28/2004	Stnlss Stl	6 "	Very Poor	Exposed	Bare
80	Brockton	346		Winter Street		5617028-1	LRMVB	07/22/2004	Wright Iron	2 "	Poor	Exposed	C. S. Casing
80	East Bridgewater			Water Street		5624958-1	LRMVB	07/14/2004	Bare Steel	2 "	Poor	Exposed	Bare
85	Brockton	181		Concord Street		5271236-1	LRMVB	07/31/2004	Cast Iron	4 "	Like New/Good	Exposed	Bare
85	Brockton	53		Edgar Street		5268930-1	LRMVB	07/31/2004	Bare Steel	2 "	Fair	Exposed	Bare
85	East Bridgewater			Bedford Street		5261975-1	LRMVB	07/31/2004	Coated Stl	3 "	Like New/Good	Exposed	Coal Tar
85	East Bridgewater			Elm Street		5271256-1	LRMVB	07/31/2004	Bare Steel	8 "	Very Poor	Exposed	Bare

Continued on next page...

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
DISTRICT: Franklin

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Foxboro	80		North Street		5635926-1	LRMB	07/22/2004	Bare Steel 6 "		Fair	Exposed	Bare
80 Medway			Cutler Street		1160934-1	LRMB	07/23/2004	Bare Steel 2 "		Fair	Exposed	Bare
80 Medway	101		Maple Street		5631046-1	LRMB	07/15/2004	Bare Steel 3 "		Very Poor	Exposed	Bare
80 Walpole			School Street		5578573-1	LRMB	07/10/2004	Bare Steel 2 "		Poor	Exposed	Bare
80 Walpole	257		School Street		5601949-1	LRMB	07/15/2004	Bare Steel 2 "		Poor	Exposed	Bare
80 Walpole	249		School Street		5633361-1	LRMB	07/20/2004	Bare Steel 2 "		Fair	Exposed	Bare
80 Wrentham	663		East Street		5618039-1	LRMB	07/07/2004	Bare Steel 6 "		Fair	Exposed	Bare
80 Wrentham	346		South		5597077-1	LRMB	07/07/2004	Bare Steel 4 "		Fair	Exposed	Bare
85 Medway	8		Brigham Street		5223216-1	LRMB	07/31/2004	Bare Steel 2 "		Fair	Exposed	Bare
85 Medway	101		Maple Lane		5244964-1	LRMB	07/31/2004	Bare Steel 3 "		Like New/Good	Exposed	Bare
85 Medway			Maple Street		5279503-1	LRMB	07/31/2004	Bare Steel 3 "		Like New/Good	Exposed	Bare
85 Medway	5		Oakland Street		5229195-1	LRMB	07/31/2004	Stnless Stl 3 "		Like New/Good	Exposed	Bare
85 Walpole	268		Common Street		5239920-1	LRMB	07/31/2004	Bare Steel 2 "		Like New/Good	Exposed	Bare
85 Walpole	39		Hoover Road		5248962-1	LRMB	07/31/2004	Bare Steel 2 "		Like New/Good	Exposed	Bare
85 Walpole	14		Maple Street		5260512-1	LRMB	07/31/2004	Bare Steel 2 "		Like New/Good	Exposed	Bare
85 Walpole	1		Woodland Road		5281310-1	LRMB	07/31/2004	Stnless Stl 3 "		Like New/Good	Exposed	Bare

Program: wwrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Hanson	334		High Street		5643036-1	LRMXB	07/30/2004	Coated Stl 4	"	Fair	Exposed	Coal Tar
80	Hanson	1287		Main Street		5603125-1	LRMXB	07/27/2004	Bare Steel 6	"	Poor	Exposed	Bare
80	Hanson	308		Maquan Street		5616916-1	LRMXB	07/08/2004	Bare Steel 3	"	Fair	Exposed	Bare
80	Hanson	220		Phillips Street		5605607-1	LRMXB	07/01/2004	Coated Stl 2	"	Fair	Exposed	Coal Tar
80	Marshfield	76		Bayberry Road		5633372-1	LRMXB	07/24/2004	Bare Steel 3	"	Very Poor	Exposed	Bare
80	Marshfield	23		Carlton Road		5611475-1	LRMXB	07/30/2004	Bare Steel 1 1/2	"	Fair	Exposed	Bare
80	Marshfield	157		Emery Road		5618043-1	LRMXB	07/12/2004	Bare Steel 1 1/2	"	Very Poor	Exposed	Bare
80	Marshfield	158		Foster Avenue		5617030-1	LRMXB	07/10/2004	Plastic	1/2	Like New/Good	New	Bare
80	Marshfield	158		Foster Avenue		5617030-1	LRMXB	07/10/2004	Bare Steel 2	"	Very Poor	Exposed	Bare
80	Marshfield	158		Foster Avenue		5617030-1	LRMXB	07/10/2004	Plastic	1/2	Fair	Retired	Bare
80	Marshfield	75		Preston Terrace		5621372-1	LRMXB	07/06/2004	Bare Steel 1 1/2	"	Fair	Exposed	Bare
80	Marshfield	190		Saginaw Avenue		5617054-1	LRMXB	07/10/2004	Bare Steel 2	"	Very Poor	Exposed	Bare
80	Norwell	28		Franklin Road		1289605-1	LRMXB	07/29/2004	Bare Steel 2	"	Very Poor	Exposed	Bare
85	Duxbury	62		Indian Trail		5228580-1	LRMXB	07/31/2004	Bare Steel 2	"	Like New/Good	Exposed	Bare
85	Hanover	515		Main Street		5225669-1	LRMXB	07/31/2004	Bare Steel 2	"	Like New/Good	Exposed	Bare
85	Hanover	272		Washington Street		5256203-1	LRMXB	07/31/2004	Bare Steel 2	"	Fair	Exposed	Bare
85	Marshfield	47		Whiting Street		5264134-1	LRMXB	07/31/2004	Bare Steel 3	"	Like New/Good	Exposed	Bare
85	Marshfield	47		Beach Street		4897242-1	LRMXB	07/31/2004	Bare Steel 3	"	Very Poor	Exposed	Bare
85	Marshfield	194		Beach Street		5286091-1	LRMXB	07/31/2004	Bare Steel 3	"	Fair	Exposed	Bare
85	Marshfield	51		Foster Avenue		5272021-1	LRMXB	07/31/2004	Bare Steel 2	"	Fair	Exposed	Bare
85	Marshfield	1308		Macker Terrace		5272044-1	LRMXB	07/31/2004	Bare Steel 1 1/2	"	Like New/Good	Exposed	Bare
85	Marshfield	68		Ocean Street		5290897-1	LRMXB	07/31/2004	Plastic	1/2	Like New/Good	New	Bare
85	Marshfield	5		Priscilla Road		5256195-1	LRMXB	07/31/2004	Coated Stl 2	"	Like New/Good	Exposed	Coal Tar
85	Pembroke	331		Westbrook Street		5276973-1	LRMXB	07/31/2004	Bare Steel 3	"	Fair	Exposed	Bare
85	Pembroke	14		Mattakeeset Street		5284246-1	LRMXB	07/31/2004	Bare Steel 4	"	Poor	Exposed	Bare
85	Scituate	24		Washington Street		5286992-1	LRMXB	07/31/2004	Bare Steel 1 1/2	"	Poor	Exposed	Bare
85	Scituate	24		Bassin Lane		5286949-1	LRMXB	07/31/2004	Bare Steel 2	"	Like New/Good	New	Bare
85	Scituate	24		Beal Place		5264482-1	LRMXB	07/31/2004	Plastic	2	Like New/Good	Exposed	Bare
85	Scituate	24		Beal Place		5264482-1	LRMXB	07/31/2004	Bare Steel 1 1/2	"	Fair	Exposed	Bare
85	Scituate	15		Beal Place		5264482-1	LRMXB	07/31/2004	Bare Steel 1 1/2	"	Fair	Retired	Bare
85	Scituate	11		Tichnor Court		5248735-1	LRMXB	07/31/2004	Bare Steel 1 1/2	"	Like New/Good	Exposed	Bare
85	Scituate	11		Tichnor Court		5248757-1	LRMXB	07/31/2004	Bare Steel 1 1/2	"	Poor	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Randolph

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Canton	36		Brooksweld Road		5621699-1	LRMXB	07/24/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
80	Canton	36		Brooksweld Road		5641629-1	LRMXB	07/30/2004	Coated Stl 2 "	2 "	Poor	Exposed	Coal Tar
80	Canton	5		Lawrence Street		5635864-1	LRMXB	07/26/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80	Sharon	55		Billings Street		5605353-1	LRMXB	07/16/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
80	Sharon	73		Billings Street		5616908-1	LRMXB	07/16/2004	Bare Steel 1 1/4 "	1 1/4 "	Fair	Exposed	Bare
80	Sharon	27		Cottage Street		5150164-1	LRMXB	07/26/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
80	Stoughton	2240		Central Street		5419603-1	LRMXB	07/06/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85	Holbrook	28		W Shore Road		5283799-1	LRMXB	07/31/2004	Coated Stl 1 "	1 "	Like New/Good	Exposed	Coal Tar
85	Randolph	3		Fairview Avenue		5277601-1	LRMXB	07/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Very Poor	Exposed	Bare
85	Sharon	81		Cottage Street		5211813-1	LRMXB	07/31/2004	Bare Steel 2 "	2 "	Like New/Good	Exposed	Bare
85	Stoughton			Drake Avenue		5261977-1	LRMXB	07/31/2004	Coated Stl 6 "	6 "	Fair	Exposed	Coal Tar

Program: wwrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Attleboro	28		Bourne Avenue	TERRY CONROY	5578522-1	LRMXB	07/12/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80	Attleboro	31		Greenhill Avenue		5632806-1	LRMXB	07/19/2004	Coated Stl 2 "	2 "	Very Poor	Exposed	Coal Tar
80	Berkley	522		Berkley Street		5198873-1	LRMXB	07/07/2004	Wright Iron 1 1/2 "	1 1/2 "	Poor	Exposed	Bare
80	Mansfield	708	710	N Main Street		5584755-1	LRMXB	07/27/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
80	Mansfield			Thompson Street		5606722-1	LRMXB	07/19/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80	Mansfield	28		Warren Avenue		5603126-1	LRMXB	07/22/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
80	Mansfield	381		Willow Street		5584656-1	LRMXB	07/28/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80	Norton	35		W Main		5596792-1	LRMXB	07/23/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
80	Seekonk	211		Fall River Avenue		5622967-1	LRMXB	07/07/2004	Bare Steel 4 "	4 "	Very Poor	Exposed	Bare
80	Seekonk	59		Ledge Road		5198878-1	LRMXB	07/29/2004	Bare Steel 4 "	4 "	Fair	Exposed	Bare
85	Attleboro	159		Mendon Road		5220554-1	LRMXB	07/31/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare
85	Attleboro			Oakhill Avenue		5292364-1	LRMXB	07/31/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare
85	Attleboro	99		Union Street		5290899-1	LRMXB	07/31/2004	Cast Iron 10 "	10 "	Fair	Exposed	Bare
85	Norton			Newcomb Street		5272915-1	LRMXB	07/31/2004	Coated Stl 6 "	6 "	Like New/Good	Exposed	Coal Tar
85	Taunton	206		Highland Street		5244966-1	LRMXB	07/31/2004	Coated Stl 8 "	8 "	Like New/Good	Exposed	Coal Tar
85	Taunton	415		Winthrop Street		5292348-1	LRMXB	07/31/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
85	Taunton	415		Winthrop Street		5292348-1	LRMXB	07/31/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare

Program: wwpt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

REPORT PARAMETERS

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 08/01/2004
To Date : 08/31/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Brockton	18		Boyden Street		5644737-1	LRMB	08/02/2004	Wright Iron 2 "	2 "	Fair	Exposed	Bare
80 Brockton	51		Irving Street		5652651-1	LRMB	08/11/2004	Bare Steel 1 1/4 "	1 1/4 "	Fair	Exposed	Bare
80 Brockton	444		Plain Street		1652217-1	LRMB	08/18/2004	Coated Stl 3/4 "	3/4 "	Like New/Good	Exposed	Coal Tar
80 East Bridgewater			Bedford Street		5650694-1	LRMB	08/21/2004	Stnless Stl 4 "	4 "	Like New/Good	Exposed	Coal Tar
80 East Bridgewater	50		Spear Avenue		5657183-1	LRMB	08/17/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80 East Bridgewater			Water Street		5657292-1	LRMB	08/17/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80 East Bridgewater			Water Street		5746603-1	LRMB	08/18/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85 Bridgewater	30		Covington Street		5291205-1	LRMB	08/31/2004	Bare Steel 2 "	2 "	Like New/Good	Exposed	Bare
85 Bridgewater	214		Summer Street		5291203-1	LRMB	08/31/2004	Bare Steel 4 "	4 "	Like New/Good	Exposed	Bare
85 Brockton	25		Claremont Avenue		5302188-1	LRMB	08/31/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85 Brockton	1435		Main Street		5295248-1	LRMB	08/31/2004	Cast Iron 3 "	3 "	Fair	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Franklin

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Franklin	79		Cottage Street		5645709-1	LRMB	08/03/2004	Bare Steel 4 "		Vary Poor	Exposed	Bare
80 Franklin	93		Cottage Street		5665480-1	LRMB	08/26/2004	Bare Steel 3 1/4 "		Fair	Exposed	Bare
80 Franklin	113		Dean Avenue		5657116-1	LRMB	08/14/2004	Bare Steel 3 "		Like New/Good	Exposed	Bare
80 Franklin			Lincoln Street		5543600-1	LRMB	08/16/2004	Bare Steel 6 "		Fair	Exposed	Bare
80 Medway	10		Guerinsey Street		5641630-1	LRMB	08/06/2004	Bare Steel 2 "		Fair	Exposed	Bare
80 Medway	235		Main Street		5577424-1	LRMB	08/07/2004	Bare Steel 4 "		Poor	Exposed	Bare
80 Walpole			Kendall Street		5606727-1	LRMB	08/16/2004	Bare Steel 2 "		Poor	Exposed	Bare
80 Walpole	1476		Washington Street		5657989-1	LRMB	08/19/2004	Bare Steel 6 "		Poor	Exposed	Bare
85 Franklin	28		Brook Street		5319507-1	LRMB	08/31/2004	Coated Stl 3 "		Like New/Good	Exposed	Coal Tar
85 Franklin	46		Wachusett Street		325595-1	LRMB	08/31/2004	Bare Steel 3 "		Fair	Exposed	Bare
85 Franklin			Wachusett Street		5311105-1	LRMB	08/31/2004	Stnlss Stl 3 "		Like New/Good	Exposed	Bare
85 Walpole	169		Kendall Street		5239925-1	LRMB	08/31/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Walpole	15		Maguire Park		5263119-1	LRMB	08/31/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Walpole	14		Maple Street		5281309-1	LRMB	08/31/2004	Bare Steel 2 "		Like New/Good	Exposed	Bare
85 Walpole	1385		Washington Street	HWY DEPT.	5225507-1	LRMB	08/31/2004	Coated Stl 1 1/4 "		Like New/Good	Exposed	Coal Tar
85 Wrentham			South Street		5314732-1	LRMB	08/31/2004	Bare Steel 4 "		Poor	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wrpt031.p
Date: 06/23/2005
Reg By: Katherine Silver
DISTRICT: Hanover

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Duxbury	35		Depot Street		5333376-1	LRMXB	08/18/2004	Coated Stl 2 "	2 "	Like New/Good	Exposed	Coal Tar
80 Hanover	1448		Hanover Street		5665446-1	LRMXB	08/26/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80 Hanson	454		E Washington		5226751-1	LRMXB	08/09/2004	Bare Steel 8 "	8 "	Fair	Exposed	Bare
80 Marshfield			Dog Lane		5656045-1	LRMXB	08/19/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
80 Marshfield			Dog Ln @ Deerhill		5642809-1	LRMXB	08/03/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
80 Marshfield	15		Dundee Drive		5650205-1	LRMXB	08/04/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
80 Marshfield	210		Elm Street		5619483-1	LRMXB	09/02/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
80 Norwell	184		High Street		5622810-1	LRMXB	08/07/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80 Scituate	8		Brown Avenue		4846101-1	LRMXB	08/03/2004	Bare Steel 1 1/2 "	1 1/2 "	Fair	Exposed	Bare
80 Scituate	810		Country Way		5653619-1	LRMXB	08/14/2004	Bare Steel 1 1/2 "	1 1/2 "	Very Poor	Exposed	Bare
80 Scituate	9		Tichnor Court		5331205-1	LRMXB	08/04/2004	Bare Steel 1 1/2 "	1 1/2 "	Very Poor	Exposed	Bare
85 Duxbury	32		Mayflower Lane		5253710-1	LRMXB	08/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Fair	Exposed	Bare
85 Hanover	1456		Barstow Avenue	service dispatch	5253691-1	LRMXB	09/31/2004	Bare Steel 2 "	2 "	Like New/Good	Exposed	Bare
85 Hanson	848		High Street		5314688-1	LRMXB	08/31/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85 Marshfield	82		Bryant Street		5293462-1	LRMXB	08/31/2004	Coated Stl 2 "	2 "	Poor	Exposed	Coal Tar
85 Marshfield	24		Carlton Road		5301979-1	LRMXB	08/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Like New/Good	Exposed	Bare
85 Marshfield	14		Preston Terrace		5300413-1	LRMXB	08/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Like New/Good	Exposed	Bare
85 Pembroke	65		Pine Tree Lane		5261979-1	LRMXB	08/31/2004	Coated Stl 2 "	2 "	Like New/Good	Exposed	Coal Tar
85 Pembroke	47		Shepherd Avenue		5296499-1	LRMXB	08/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Very Poor	Exposed	Bare
85 Pembroke	331		Washington Street		5292420-1	LRMXB	08/31/2004	Bare Steel 4 "	4 "	Fair	Exposed	Bare
85 Pembroke	138		Water Street		5212946-1	LRMXB	08/31/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85 Scituate	796		Country Way		5295010-1	LRMXB	08/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Fair	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
DISTRICT: Randolph

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Canton	15		Kempley Street		5657020-1	LRMB	08/20/2004	Stnls Stl 1 1/4 "	Very Poor	Exposed	Bare
80 Easton	50		Center Street		5657109-1	LRMB	08/16/2004	Bare Steel 2 "	Poor	Exposed	Bare
80 Easton	149		Pine Street		1554607-1	LRMB	08/28/2004	Bare Steel 4 "	Poor	Exposed	Bare
80 Easton	30		Seaver Street		5616912-1	LRMB	08/03/2004	Bare Steel 2 "	Fair	Exposed	Bare
80 Holbrook	246		South Street		5654248-1	LRMB	08/25/2004	Bare Steel 6 "	Fair	Exposed	Bare
80 Stoughton			Central St		5617025-1	LRMB	08/18/2004	Bare Steel 4 "	Poor	Exposed	Bare
80 Stoughton			Morton Square		5659713-1	LRMB	08/31/2004	Plastic 2 "	Like New/Good	Exposed	Bare
80 Stoughton			Morton Square		5659713-1	LRMB	08/31/2004	Plastic 2 "	Like New/Good	Retired	Bare
80 Stoughton			Morton Square		5659713-1	LRMB	08/31/2004	Plastic 2 "	Like New/Good	New	Bare
80 Stoughton	11		Pearl Street		5661814-1	LRMB	08/24/2004	Bare Steel 3 "	Poor	Exposed	Bare
80 Stoughton	103		Water Street		5652742-1	LRMB	08/24/2004	Stnls Stl 6 "	Very Poor	Exposed	Bare
80 Stoughton	184	0	Willow Street		5578570-1	LRMB	08/07/2004	Bare Steel 1 1/4 "	Very Poor	Exposed	Bare
80 Stoughton	192		Willow Street		5651816-1	LRMB	08/23/2004	Bare Steel 1 1/2 "	Very Poor	Exposed	Bare
85 Canton			Washington Street		5291189-1	LRMB	08/31/2004	Coated Stl 6 "	Fair	Exposed	Coal Tar
85 Canton	833		Washington Street		5296091-1	LRMB	08/31/2004	Bare Steel 1 "	Poor	Exposed	Bare
85 Randolph	50		Orchard Street		5285812-1	LRMB	08/31/2004	Bare Steel 2 "	Poor	Exposed	Bare
85 Randolph	8		S Harriette Street		5285814-1	LRMB	08/31/2004	Bare Steel 1 1/4 "	Fair	Exposed	Bare
85 Sharon			Upland Road		5302043-1	LRMB	08/31/2004	Bare Steel 2 "	Poor	Exposed	Bare
85 Stoughton	36		Belmont Avenue		5190847-1	LRMB	08/31/2004	Bare Steel 1 1/4 "	Like New/Good	Exposed	Bare
85 Stoughton	78		Brock Street		5299619-1	LRMB	08/31/2004	Bare Steel 6 "	Like New/Good	Exposed	Bare
85 Stoughton	9		Doty Drive		5206508-1	LRMB	08/31/2004	Bare Steel 2 "	Like New/Good	Exposed	Bare

Continued on next page...

Program: wvpt031.p
Date: 06/23/2005
Req By: Katherine Silver
DISTRICT: Taunton
Bay State Gas Company
Work Order Management System
Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Attleboro			Brown Street		5556787-1	LRMB	08/05/2004	Bare Steel 3 "	"	Fair	Exposed	Bare
80 Lakeville	10		Taunton Street		5652683-1	LRMB	08/20/2004	Stnless Stl 6 "	"	Poor	Exposed	Bare
80 Mansfield	67		Warren Avenue		5658468-1	LRMB	08/30/2004	Bare Steel 2 "	"	Very Poor	Exposed	Bare
80 Norton			Maple Street		5640517-1	LRMB	08/06/2004	Coated Stl 4 "	"	Like New/Good	Exposed	Coal Tar
80 Norton			S Worcester Street		5640557-1	LRMB	08/07/2004	Coated Stl 8 "	"	Fair	Exposed	Coal Tar
80 Seekonk	45		County Street		5649471-1	LRMB	08/20/2004	Bare Steel 2 "	"	Fair	Exposed	Bare
80 Seekonk	17	19	County Street		5650438-1	LRMB	08/20/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
80 Seekonk			County Street		5652840-1	LRMB	08/20/2004	Stnless Stl 2 "	"	Fair	Exposed	Bare
80 Seekonk	999		Fall River Avenue		5624038-1	LRMB	08/11/2004	Bare Steel 4 "	"	Poor	Exposed	Bare
80 Seekonk	89		Fall River Avenue		5624041-1	LRMB	08/06/2004	Bare Steel 2 "	"	Fair	Exposed	Bare
80 Seekonk	394		Taunton Avenue		5624030-1	LRMB	08/11/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
80 Taunton	4		Chase Street		5655589-1	LRMB	08/14/2004	Wright Iron 2 "	"	Poor	Exposed	Bare
80 Taunton	22		Hart Street		5622815-1	LRMB	08/04/2004	Wright Iron 6 "	"	Fair	Exposed	Bare
80 Taunton	177		Highland Street		5652699-1	LRMB	08/23/2004	Bare Steel 8 "	"	Poor	Exposed	Bare
80 Taunton			Short Street		5657844-1	LRMB	08/28/2004	Bare Steel 2 "	"	Very Poor	Exposed	Bare
85 Attleboro	47		Emory Street		4522282-1	LRMB	08/31/2004	Bare Steel 8 "	"	Like New/Good	Exposed	Bare
85 Attleboro	18		Emory Street		4522267-1	LRMB	08/31/2004	Bare Steel 8 "	"	Like New/Good	Exposed	Bare
85 Attleboro	117		Fisher Avenue		5286984-1	LRMB	08/31/2004	Bare Steel 4 "	"	Fair	Exposed	Bare
85 Norton			W Main Street		5284750-1	LRMB	08/31/2004	Bare Steel 6 "	"	Very Poor	Exposed	Bare
85 Seekonk			Hope Street		5298699-1	LRMB	08/31/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
85 Seekonk	184		Newman Avenue		5260509-1	LRMB	08/31/2004	Bare Steel 4 "	"	Poor	Exposed	Bare
85 Taunton	70		E Water Street		5297523-1	LRMB	08/31/2004	Bare Steel 6 "	"	Poor	Exposed	Bare
85 Taunton	81		Scadding Street		5296098-1	LRMB	08/31/2004	Plastic 4 "	"	Like New/Good	New	Bare
85 Taunton	81		Scadding Street		5296098-1	LRMB	08/31/2004	Plastic 4 "	"	Like New/Good	Exposed	Bare
85 Taunton	414	417	Winthrop Street		5291204-1	LRMB	08/31/2004	Bare Steel 3 "	"	Poor	Exposed	Bare
85 Taunton	414	417	Winthrop Street		5291204-1	LRMB	08/31/2004	Bare Steel 2 "	"	Very Poor	Exposed	Bare
85 Taunton	223		Worcester Street		5304046-1	LRMB	08/31/2004	Bare Steel 2 "	"	Fair	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 98 Orders in this report.

End of Report

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

REPORT PARAMETERS

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 09/01/2004
To Date : 09/30/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Bridgewater	70		Dean Street		5869280-1	LRMB	09/14/2004	Bare Steel 2 "	Fair	Exposed	Bare
80 Brockton	40		Juneau Road		5889181-1	LRMB	09/25/2004	Coated Stl 2 "	Like New/Good	Exposed	Coal Tar
80 Brockton			Manomet Street		5679905-1	LRMB	09/13/2004	Bare Steel 2 "	Very Poor	Exposed	Bare
80 Brockton			Manomet Street		5893604-1	LRMB	09/30/2004	Bare Steel 2 "	Very Poor	Exposed	Bare
80 East Bridgewater	14		Adams Lane		5869281-1	LRMB	09/11/2004	Coated Stl 3/4 "	Fair	Exposed	Coal Tar
80 East Bridgewater			Matfield Street		5675942-1	LRMB	09/14/2004	Screw End 4 "	Poor	Exposed	Bare
85 Brockton	120		Grove Street		5331206-1	LRMB	09/30/2004	Cast Iron 6 "	Fair	Exposed	Bare
85 Brockton	160		Manomet Street		5327979-1	LRMB	09/30/2004	Bare Steel 2 "	Fair	Exposed	Bare
85 Brockton	57		Stebbins		5326371-1	LRMB	09/30/2004	Plastic 1 1/4 "	Like New/Good	New	Bare
85 Brockton	57		Stebbins		5326371-1	LRMB	09/30/2004	Plastic 1 1/4 "	Like New/Good	Exposed	Bare
85 Brockton	57		Stebbins		5326371-1	LRMB	09/30/2004	Plastic 1 1/4 "	Like New/Good	Retired	Bare
85 East Bridgewater			Central Street		4897285-1	LRMB	09/30/2004	Bare Steel 6 "	Fair	Exposed	Bare
85 East Bridgewater	175		Central Street		5291239-1	LRMB	09/30/2004	Bare Steel 6 "	Like New/Good	Exposed	Bare
85 West Bridgewater	311		River Street		4897314-1	LRMB	09/30/2004	Bare Steel 2 "	Like New/Good	Exposed	Bare
85 West Bridgewater			River Street		5326670-1	LRMB	09/30/2004	Bare Steel 2 "	Fair	Exposed	Bare
85 West Bridgewater			S Main Street		5299439-1	LRMB	09/30/2004	Bare Steel 2 "	Fair	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
DISTRICT: Franklin

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Foxboro			Carpenter Street		5659388-1	LRMXX	09/17/2004	Coated Stl 2 "		Like New/Good	Exposed	Coal Tar
80	Foxboro	114		Main Street		5675943-1	LRMXX	09/13/2004	Bare Steel 6 "		Fair	Exposed	Bare
80	Foxboro			Opp 330 Central Street		5673165-1	LRMXX	09/11/2004	Bare Steel 6 "		Poor	Exposed	Bare
80	Franklin	2		Mill River Circle		5671704-1	LRMXX	09/13/2004	Plastic 1/2 "		Fair	Exposed	Bare
80	Franklin	110		Park Road		5669555-1	LRMXX	09/10/2004	Stnlss Stl 2 "		Very Poor	Exposed	Bare
80	Franklin	23		Summer Street		5674914-1	LRMXX	09/05/2004	Bare Steel 2 "		Poor	Exposed	Bare
80	Franklin	33	35	Washington Street		5694681-1	LRMXX	09/27/2004	Bare Steel 4 "		Very Poor	Exposed	Bare
80	Medway	8		Country Lane		5606723-1	LRMXX	09/08/2004	Bare Steel 2 "		Poor	Exposed	Bare
80	Medway	19		Maple Street		5669286-1	LRMXX	09/20/2004	Bare Steel 3 "		Very Poor	Exposed	Bare
80	Walpole	274		East Street		5261793-1	LRMXX	09/11/2004	Bare Steel 6 "		Like New/Good	Exposed	Bare
80	Walpole	1280		Washington Street		5685983-1	LRMXX	09/25/2004	Stnlss Stl 6 "		Poor	Exposed	Bare
85	Bellingham	159		Hartford Avenue		2080188-1	LRMXX	09/30/2004	Coated Stl 4 "		Fair	Exposed	Coal Tar
85	Bellingham	159		Hartford Avenue		5301098-1	LRMXX	09/30/2004	Coated Stl 4 "		Fair	Exposed	Coal Tar
85	Foxboro	81		Carpenter Street		5233899-1	LRMXX	09/30/2004	Bare Steel 2 "		Like New/Good	Exposed	Bare
85	Foxboro	328		Central Street		5330360-1	LRMXX	09/30/2004	Bare Steel 6 "		Poor	Exposed	Bare
85	Foxboro	71		Cross Street		5330365-1	LRMXX	09/30/2004	Coated Stl 2 "		Like New/Good	Exposed	Coal Tar
85	Foxboro	9		Maple Place		5248884-1	LRMXX	09/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Foxboro	143		Mechanic Street		5330353-1	LRMXX	09/30/2004	Bare Steel 4 "		Poor	Exposed	Bare
85	Foxboro			North Street		5346082-1	LRMXX	09/30/2004	Bare Steel 6 "		Poor	Exposed	Bare
85	Foxboro	111		South Street		5321973-1	LRMXX	09/30/2004	Bare Steel 3/4 "		Poor	Exposed	Bare
85	Foxboro	96		South Street		5321992-1	LRMXX	09/30/2004	Bare Steel 3 "		Fair	Exposed	Bare
85	Foxboro	97		South Street		5321995-1	LRMXX	09/30/2004	Bare Steel 3 "		Fair	Exposed	Bare
85	Franklin			Main Street		5331770-1	LRMXX	09/30/2004	Bare Steel 6 "		Very Poor	Exposed	Bare
85	Franklin	59		Pleasant Street		5248979-1	LRMXX	09/30/2004	Bare Steel 3 "		Very Poor	Exposed	Bare
85	Walpole	15		Maguire Park		5321977-1	LRMXX	09/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Walpole	23		Prospect Street		121041-1	LRMXX	09/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Walpole	25		Prospect Street		5322125-1	LRMXX	09/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85	Walpole	16		Rhoades Avenue		1601941-1	LRMXX	09/30/2004	Bare Steel 2 "		Poor	Exposed	Bare
85	Wrentham	719		East Street		5314677-1	LRMXX	09/30/2004	Bare Steel 6 "		Fair	Exposed	Bare

Continued on next page...

Program: wwrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Hanson			High Street		4897301-1	LRMB	09/15/2004	Bare Steel 4	"	Poor	Exposed	Bare
80	Hanson			High Street		4897301-1	LRMB	09/15/2004	Bare Steel 2	"	Very Poor	Retired	Bare
80	Hanson			High Street		4897301-1	LRMB	09/15/2004	Coated Stl 2	"	Like New/Good	New	Coal Tar
80	Hanson	334		High Street		5661742-1	LRMB	09/01/2004	Bare Steel 4	"	Poor	Exposed	Bare
80	Marshfield			Field Street		5687796-1	LRMB	09/21/2004	Coated Stl 2	"	Like New/Good	Exposed	Coal Tar
80	Scituate	11		Curtis Street		5699895-1	LRMB	09/30/2004	Bare Steel 2	"	Fair	Exposed	Bare
80	Scituate			Glades Road		5695842-1	LRMB	09/20/2004	Bare Steel 2	"	Fair	Exposed	Bare
80	Scituate	1		Second Avenue		5691242-1	LRMB	09/25/2004	Plastic 6	"	Fair	Exposed	Bare
80	Scituate	6		Utility Road		5685774-1	LRMB	09/17/2004	Bare Steel 1 1/2	"	Poor	Exposed	Bare
85	Duxbury	63		Upland Road		5302045-1	LRMB	09/30/2004	Bare Steel 2	"	Like New/Good	Exposed	Bare
85	Hanson	848		High Street		5336304-1	LRMB	09/30/2004	Bare Steel 4	"	Fair	Exposed	Bare
85	Marshfield	77		Bryant Street		5342435-1	LRMB	09/30/2004	Bare Steel 2	"	Poor	Exposed	Bare
85	Marshfield	85		Chandler Drive		5328867-1	LRMB	09/30/2004	Coated Stl 2	"	Like New/Good	Exposed	Coal Tar
85	Marshfield	106		Ferry Hill Road		5297667-1	LRMB	09/30/2004	Stnls Stl 1 1/2	"	Like New/Good	Exposed	Bare
85	Marshfield	51		Macker Terrace		5338998-1	LRMB	09/30/2004	Bare Steel 1 1/2	"	Fair	Exposed	Bare
85	Marshfield	1574		Ocean Street		5338709-1	LRMB	09/30/2004	Coated Stl 6	"	Fair	Exposed	Coal Tar
85	Marshfield	1574		Ocean Street		5338709-1	LRMB	09/30/2004	Coated Stl 6	"	Fair	Exposed	Coal Tar
85	Marshfield	1574		Ocean Street		5338709-1	LRMB	09/30/2004	Plastic 1 1/2	"	Fair	Retired	Bare
85	Norwell	41		Franklin Road		5327951-1	LRMB	09/30/2004	Bare Steel 2	"	Like New/Good	New	Bare
85	Norwell	47		Gerard Road		5311165-1	LRMB	09/30/2004	Coated Stl 2	"	Very Poor	Exposed	Bare
85	Pembroke	233		Bonney Street		5284489-1	LRMB	09/30/2004	Coated Stl 2	"	Like New/Good	Exposed	Bare
85	Pembroke	233		Mattakeesett Street		5264485-1	LRMB	09/30/2004	Coated Stl 2	"	Like New/Good	Exposed	Coal Tar
85	Pembroke	233		Mattakeesett Street		5264485-1	LRMB	09/30/2004	Bare Steel 1 1/2	"	Very Poor	Exposed	Bare
85	Pembroke	233		Mattakeesett Street		5264485-1	LRMB	09/30/2004	Bare Steel 1 1/2	"	Very Poor	Retired	Bare
85	Pembroke	60		Pinetree Lane		5261981-1	LRMB	09/30/2004	Plastic 1 1/4	"	Like New/Good	New	Bare
85	Pembroke	92		Wintergreen Farm Road		5342726-1	LRMB	09/30/2004	Coated Stl 2	"	Fair	Exposed	Coal Tar
85	Scituate	40		Grasshopper Lane		5326474-1	LRMB	09/30/2004	Bare Steel 1 1/2	"	Like New/Good	Exposed	Bare
85	Scituate	40		Grasshopper Lane		5326474-1	LRMB	09/30/2004	Bare Steel 1 1/2	"	Very Poor	Exposed	Bare
85	Scituate	40		Grasshopper Lane		5326474-1	LRMB	09/30/2004	Plastic 1 1/2	"	Fair	Retired	Bare
85	Scituate	40		Grasshopper Lane		5326474-1	LRMB	09/30/2004	Plastic 1 1/2	"	Like New/Good	New	Bare
85	Scituate	633		Hatherly Road		5330279-1	LRMB	09/30/2004	Bare Steel 1 1/4	"	Fair	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Randolph

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Canton	14		Greenbriar Road		5673163-1	LRMXB	09/14/2004	Coated Stl 2	2 "	Fair	Exposed	Coal Tar
80 Easton			Rockland Street		5683549-1	LRMXB	09/25/2004	Coated Stl 2	2 "	Fair	Exposed	Coal Tar
80 Sharon	32		Ames Street		5624951-1	LRMXB	09/21/2004	Coated Stl 2	2 "	Fair	Exposed	Coal Tar
80 Sharon	186		Maskwonicut Street		5683550-1	LRMXB	09/22/2004	Bare Steel 1	1 1/2 "	Fair	Exposed	Bare
80 Sharon			Massapoag Avenue		5678391-1	LRMXB	09/12/2004	Bare Steel 2	2 "	Fair	Exposed	Bare
80 Sharon			Oak Hill Drive		5673166-1	LRMXB	09/14/2004	Coated Stl 2	2 "	Fair	Exposed	Coal Tar
80 Sharon			Oakhill Drive		5671816-1	LRMXB	09/14/2004	Coated Stl 2	2 "	Fair	Exposed	Coal Tar
80 Sharon			Upland Road		5683243-1	LRMXB	09/16/2004	Bare Steel 2	2 "	Very Poor	Exposed	Bare
80 Stoughton	27		Woodland Street		5691251-1	LRMXB	09/27/2004	Bare Steel 1	1 1/4 "	Fair	Exposed	Bare
80 Stoughton			Canton Street		5527762-1	LRMXB	09/23/2004	Bare Steel 6	6 "	Fair	Exposed	Bare
80 Stoughton			Canton Street		5527762-1	LRMXB	09/23/2004	Bare Steel 6	6 "	Very Poor	Retired	Bare
80 Stoughton	117		Canton Street		5527762-1	LRMXB	09/23/2004	Plastic	6 "	Like New/Good	New	Bare
80 Stoughton			Jamie Lane		5692566-1	LRMXB	09/26/2004	Plastic	1/2 "	Like New/Good	Exposed	Bare
85 Canton			Monk Street		5192930-1	LRMXB	09/07/2004	Bare Steel 2	2 "	Fair	Exposed	Bare
85 Canton	92		Lawrence Street		5325643-1	LRMXB	09/30/2004	Bare Steel 2	2 "	Very Poor	Exposed	Bare
85 Canton			Randolph Street		5327927-1	LRMXB	09/30/2004	Coated Stl 2	2 "	Fair	Exposed	Coal Tar
85 Canton			Savin Hill Street		5342417-1	LRMXB	09/30/2004	Coated Stl 2	2 "	Fair	Exposed	Bare
85 Canton			Washington Street		5332708-1	LRMXB	09/30/2004	Bare Steel 1	1 "	Poor	Exposed	Bare
85 Easton	5		Seaver Street		5298523-1	LRMXB	09/30/2004	Bare Steel 3	3 "	Very Poor	Exposed	Bare
85 Randolph	15		High Street		5311170-1	LRMXB	09/30/2004	Bare Steel 2	2 "	Like New/Good	Exposed	Bare
85 Randolph			High Street		5328863-1	LRMXB	09/30/2004	Coated Stl 2	2 "	Like New/Good	Exposed	Coal Tar
85 Randolph	40		Wilmarth Road		5317382-1	LRMXB	09/30/2004	Coated Stl 2	2 "	Poor	Exposed	Coal Tar
85 Randolph			Wilmarth Road		5326481-1	LRMXB	09/30/2004	Bare Steel 1	1 1/2 "	Like New/Good	Exposed	Bare
85 Sharon			Upland Road		5311153-1	LRMXB	09/30/2004	Bare Steel 2	2 "	Fair	Exposed	Bare
85 Stoughton	2070		Central Street		5320859-1	LRMXB	09/30/2004	Bare Steel 2	2 "	Poor	Exposed	Bare
								Bare Steel 6	6 "	Fair	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Attleboro	142		Brown Street		5689086-1	LRMB	09/22/2004	Bare Steel 4 "	"	Poor	Exposed	Bare
80 Attleboro	142		Brown Street		5689083-1	LRMB	09/22/2004	Bare Steel 3/4 "	"	Poor	Exposed	Bare
80 Attleboro	142		Brown Street		5689086-1	LRMB	09/22/2004	Bare Steel 3/4 "	"	Poor	Retired	Bare
80 Norton	284		S Worcester Street		5682635-1	LRMB	09/07/2004	Bare Steel 8 "	"	Poor	Exposed	Bare
80 Norton	278		Worcester Street		5682636-1	LRMB	09/07/2004	Bare Steel 8 "	"	Poor	Exposed	Bare
80 Taunton	427		Winthrop Street		5652700-1	LRMB	09/07/2004	Bare Steel 2 "	"	Like New/Good	Exposed	Bare
85 Attleboro	37		Bourne Avenue		5340105-1	LRMB	09/30/2004	Bare Steel 2 "	"	Fair	Exposed	Bare
85 Attleboro	846		Oakhill Avenue		5336056-1	LRMB	09/30/2004	Bare Steel 4 "	"	Fair	Exposed	Bare
85 Attleboro			Washington Street		5291222-1	LRMB	09/30/2004	Bare Steel 2 "	"	Fair	Exposed	Bare
85 Dighton	71		Forest Street		5327974-1	LRMB	09/30/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
85 Dighton	83		Forest Street		5327977-1	LRMB	09/30/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
85 Lakeville	64		Taunton Street		5338683-1	LRMB	09/30/2004	Bare Steel 6 "	"	Poor	Exposed	Bare
85 Mansfield			Chilson Avenue		5331957-1	LRMB	09/30/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
85 Norton			Freeman Street		5307606-1	LRMB	09/30/2004	Bare Steel 6 "	"	Poor	Exposed	Bare
85 Norton	29		Mansfield Avenue		5284775-1	LRMB	09/30/2004	Bare Steel 6 "	"	Fair	Exposed	Bare
85 Norton	71		N Worcester Street		5294417-1	LRMB	09/30/2004	Bare Steel 2 "	"	Very Poor	Exposed	Bare
85 Norton	55		W Main Street		5325531-1	LRMB	09/30/2004	Bare Steel 6 "	"	Fair	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 117 Orders in this report.

End of Report

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

REPORT PARAMETERS

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 10/01/2004
To Date : 10/31/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wwpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Bridgewater	49		South Street		5645686-1	LRMXB	10/07/2004	Coated Stl	1 "	Like New/Good	Exposed	Coal Tar
80	Brockton	80		Brook Street		5709146-1	LRMXB	10/12/2004	Bare Steel	1 1/4 "	Very Poor	Exposed	Bare
80	Brockton	59		Clarence Street		1690377-1	LRMXB	10/28/2004	Cast Iron	4 "	Fair	Exposed	
85	Bridgewater			Clarence Ave-summer St		5385103-1	LRMXB	10/31/2004	Plastic	2 "	Like New/Good	Exposed	Bare
85	Brockton	41		Bates Street		4950665-1	LRMXB	10/31/2004	Bare Steel	8 "	Fair	Exposed	Bare
85	Brockton	27		Condon Street		5327980-1	LRMXB	10/31/2004	Bare Steel	1 1/4 "	Very Poor	Exposed	Bare
85	Brockton			Pine Street		5365357-1	LRMXB	10/31/2004	Coated Stl	8 "	Like New/Good	Exposed	Coal Tar

Continued on next page...

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Franklin

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Franklin	33		Chestnut Street		5618054-1	LRMB	10/05/2004	Bare Steel 3 "		Very Poor	Exposed	Bare
80 Franklin	33		Corbin Street		5610378-1	LRMB	10/29/2004	Bare Steel 2 "		Poor	Exposed	Bare
80 Franklin	11		Haverstock Road		5689183-1	LRMB	10/01/2004	Coated Stl 2 "		Fair	Exposed	Bare
80 Franklin			Hillside Road		5574571-1	LRMB	10/26/2004	Bare Steel 2 "		Very Poor	Exposed	Bare
80 Franklin			Wachusett Street		5697736-1	LRMB	10/12/2004	Bare Steel 4 "		Very Poor	Exposed	Bare
80 Franklin	35		Washington Street		5716484-1	LRMB	10/22/2004	Bare Steel 4 "		Poor	Exposed	Bare
80 Medway			Lincoln & Wellington		5699932-1	LRMB	10/04/2004	Coated Stl 2 "		Like New/Good	New	Coal Tar
80 Medway			Lincoln & Wellington		5699932-1	LRMB	10/04/2004	Coated Stl 2 "		Like New/Good	Exposed	Epoxy
80 Medway			Lincoln & Wellington		5699932-1	LRMB	10/04/2004	Coated Stl 2 "		Very Poor	Retired	Epoxy
80 Walpole	7		Allston Drive		5714496-1	LRMB	10/16/2004	Coated Stl 2 "		Fair	Exposed	Coal Tar
80 Walpole	7		Chickering Lane		5710656-1	LRMB	10/20/2004	Coated Stl 2 "		Like New/Good	New	Coal Tar
80 Walpole	7		Chickering Lane		5710656-1	LRMB	10/20/2004	Coated Stl 2 "		Like New/Good	Exposed	Coal Tar
80 Walpole	7		Chickering Lane		5710656-1	LRMB	10/20/2004	Coated Stl 2 "		Like New/Good	Exposed	Coal Tar
80 Walpole	15		Ellis Street		5702554-1	LRMB	10/12/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Foxboro	69		Carpenter Street		5288527-1	LRMB	10/31/2004	Bare Steel 2 "		Very Poor	Exposed	Bare
85 Foxboro	135		Chestnut Street		1667971-1	LRMB	10/31/2004	Coated Stl 8 "		Like New/Good	Exposed	Coal Tar
85 Foxboro			Chestnut Street		5390271-1	LRMB	10/31/2004	Bare Steel 6 "		Very Poor	Exposed	Bare
85 Foxboro			Granite Street		1446300-1	LRMB	10/31/2004	Coated Stl 2 "		Fair	Exposed	Coal Tar
85 Foxboro	100		Granite Street		4504449-1	LRMB	10/31/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Foxboro	106		Granite Street		5291212-1	LRMB	10/31/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Foxboro	211		Mechanic Street		5349811-1	LRMB	10/31/2004	Bare Steel 4 "		Poor	Exposed	Bare
85 Foxboro	157		Mechanic Street		5360090-1	LRMB	10/31/2004	Coated Stl 4 "		Poor	Exposed	Coal Tar
85 Foxboro	159		Mechanic Street		5369167-1	LRMB	10/31/2004	Bare Steel 4 "		Poor	Exposed	Bare
85 Franklin			Fisher Street		5368936-1	LRMB	10/31/2004	Bare Steel 3 "		Poor	Exposed	Bare
85 Franklin	164		Main Street		5369036-1	LRMB	10/31/2004	Bare Steel 6 "		Poor	Exposed	Bare
85 Medway	2	4	River Street		5229204-1	LRMB	10/31/2004	Coated Stl 2 "		Like New/Good	Exposed	Coal Tar
85 Walpole	15		Maguire Park		5354739-1	LRMB	10/31/2004	Bare Steel 2 "		Very Poor	Exposed	Bare
85 Walpole	25		Prospect Street		5341193-1	LRMB	10/31/2004	Bare Steel 2 "		Fair	Exposed	Bare

Program: wvpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Duxbury	146		Crescent Street		5662610-1	LRMXB	10/06/2004	Bare Steel 2 "	2 "	Like New/Good	Exposed	Bare
80	Scituate	81		Country Way		5727868-1	LRMXB	10/28/2004	Coated Stl 1 "	1 "	Like New/Good	Exposed	Coal Tar
85	Duxbury	18		Carr Road		1528098-1	LRMXB	10/31/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85	Hanson	33		Mattakesett Street		5367719-1	LRMXB	10/31/2004	Bare Steel 4 "	4 "	Very Poor	Exposed	Bare
85	Norwell	49		Dana Road		5359881-1	LRMXB	10/31/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85	Norwell	41		Franklin Road		5387991-1	LRMXB	10/31/2004	Bare Steel 2 "	2 "	Like New/Good	Exposed	Bare
85	Pembroke	233		Mattakesett Street		5333958-1	LRMXB	10/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Fair	Exposed	Bare
85	Pembroke			Union Street		4100623-1	LRMXB	10/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Very Poor	Exposed	Bare
85	Pembroke			Union Street		4100623-1	LRMXB	10/31/2004	Plastic 1 1/2 "	1 1/2 "	Like New/Good	New	Bare
85	Pembroke			Union Street		5372479-1	LRMXB	10/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Fair	Exposed	Bare
85	Pembroke	547		Washington Street		5339977-1	LRMXB	10/31/2004	Plastic 2 "	2 "	Fair	Exposed	Bare
85	Scituate	80		Brook Street		5362370-1	LRMXB	10/31/2004	Bare Steel 4 "	4 "	Very Poor	Exposed	Bare
85	Scituate	796		Country Way		5297669-1	LRMXB	10/31/2004	Bare Steel 1 1/2 "	1 1/2 "	Very Poor	Exposed	Bare

Continued on next page...

Program: wwrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Randolph

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Randolph	21		Maple Street		4472168-1	LRMVB	10/14/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
80 Randolph	18		Milton Terrace		5698955-1	LRMVB	10/07/2004	Bare Steel 2 "	2 "	Like New/Good	Exposed	Bare
80 Sharon	186		Maskwonicut		5702542-1	LRMVB	10/08/2004	Bare Steel 1 1/2 "	1 1/2 "	Fair	Exposed	Bare
80 Stoughton	2232		Central Street		5715306-1	LRMVB	10/30/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
80 Stoughton	49		Grove Street		5691248-1	LRMVB	10/04/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
80 Stoughton	11		Pearl Street		5673169-1	LRMVB	10/02/2004	Bare Steel 3 "	3 "	Fair	Exposed	Bare
80 Stoughton	33		Record Street		5710276-1	LRMVB	10/07/2004	Bare Steel 1 1/2 "	1 1/2 "	Fair	Exposed	Bare
85 Canton	92		Lawrence Street		5358862-1	LRMVB	10/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85 Canton	59		Walpole Street		5358689-1	LRMVB	10/31/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85 Canton			Washington Street		4701423-1	LRMVB	10/31/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare
85 Canton			Washington Street		4701423-1	LRMVB	10/31/2004	Bare Steel 3 "	3 "	Poor	Retired	Bare
85 Easton	86		Center Street		5374244-1	LRMVB	10/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85 Easton	480		Turnpike Street		5372625-1	LRMVB	10/31/2004	Plastic 1 1/4 "	1 1/4 "	Like New/Good	Exposed	Bare
85 Holbrook			Belcher Street		5327944-1	LRMVB	10/31/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
85 Holbrook	7		Spring Street		5349906-1	LRMVB	10/31/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85 Randolph	19	21	Martin Terrace		5385220-1	LRMVB	10/31/2004	Bare Steel 2 "	2 "	Like New/Good	Exposed	Bare
85 Sharon	31		Bayberry Drive		5304061-1	LRMVB	10/31/2004	Coated Stl 1 1/2 "	1 1/2 "	Fair	Exposed	Coal Tar
85 Sharon			Billings Street		5384964-1	LRMVB	10/31/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85 Sharon	357		N Main Street		5351585-1	LRMVB	10/31/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare
85 Sharon			Upland Road		5351659-1	LRMVB	10/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85 Stoughton	110		Bay Road		5337798-1	LRMVB	10/31/2004	Bare Steel 6 "	6 "	Like New/Good	Exposed	Bare
85 Stoughton			Doty Drive		5384958-1	LRMVB	10/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85 Stoughton	1155		Park Street		5339900-1	LRMVB	10/31/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85 Stoughton	134		Willow Street		5339948-1	LRMVB	10/31/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Attleboro	1503		Park Street		569897-1	LRMVB	10/01/2004	Bare Steel	4 "	Poor	Exposed	Bare
80	Norton			Norton Glen Road		5702501-1	LRMVB	10/20/2004	Coated Stl	1 "	Like New/Good	New	Coal Tar
80	Norton			Norton Glen Road		5702501-1	LRMVB	10/20/2004	Coated Stl	1 "	Like New/Good	Exposed	Coal Tar
80	Norton			Norton Glen Road		5702501-1	LRMVB	10/20/2004	Coated Stl	1 "	Like New/Good	Retired	Coal Tar
80	Raynham	300		Cape Highway		5710625-1	LRMVB	10/13/2004	Plastic	1 1/4 "	Like New/Good	Exposed	Bare
80	Raynham	300		Cape Highway		5710625-1	LRMVB	10/13/2004	Plastic	1 1/4 "	Like New/Good	Retired	Bare
80	Raynham	300		Cape Highway		5710625-1	LRMVB	10/13/2004	Plastic	1 1/4 "	Like New/Good	Retired	Bare
80	Taunton			Arlington Street		5702250-1	LRMVB	10/06/2004	Coated Stl	6 "	Like New/Good	Exposed	Coal Tar
80	Taunton	122		Hart Street		5698830-1	LRMVB	10/01/2004	Plastic	6 "	Like New/Good	Exposed	Bare
80	Taunton	4		Maple Avenue		5726253-1	LRMVB	10/28/2004	Cast Iron	3 "	Poor	Exposed	Bare
85	Attleboro			Curtis Avenue		5321965-1	LRMVB	10/31/2004	Bare Steel	3 "	Fair	Exposed	Bare
85	Attleboro	78		North Avenue		4967254-1	LRMVB	10/31/2004	Bare Steel	6 "	Fair	Exposed	Bare
85	Attleboro	795		Park Street		5362256-1	LRMVB	10/31/2004	Bare Steel	4 "	Fair	Exposed	Bare
85	Attleboro	415		Robinson Avenue		5321381-1	LRMVB	10/31/2004	Bare Steel	3 "	Fair	Exposed	Bare
85	Dighton			Main Street		5344954-1	LRMVB	10/31/2004	Wright Iron	1 1/2 "	Poor	Exposed	Bare
85	Mansfield	28		Henry Street		5365373-1	LRMVB	10/31/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
85	Mansfield			Janet Lane		5360092-1	LRMVB	10/31/2004	Coated Stl	2 "	Like New/Good	Exposed	Coal Tar
85	Mansfield			Oakland Street		5336071-1	LRMVB	10/31/2004	Bare Steel	3/4 "	Fair	Exposed	Bare
85	Norton			Mansfield Avenue		5294419-1	LRMVB	10/31/2004	Bare Steel	6 "	Fair	Exposed	Bare
85	Norton	464		S Worcester Street		5389913-1	LRMVB	10/31/2004	Bare Steel	8 "	Poor	Exposed	Bare
85	Norton	402		S Worcester Street		5376965-1	LRMVB	10/31/2004	Coated Stl	2 "	Like New/Good	Exposed	Coal Tar
85	Norton	83		S Worcester Street		5452043-1	LRMVB	10/31/2004	Bare Steel	8 "	Fair	Exposed	Bare
85	Seekonk	30		Newman Avenue		5144060-1	LRMVB	10/31/2004	Bare Steel	2 "	Fair	Exposed	Bare

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wrpt031.P
Date: 06/23/2005
Req By: Katherine Silver
There are 95 Orders in this report.

End of Report

Program: wrpt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

R E P O R T P A R A M E T E R S

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 11/01/2004
To Date : 11/30/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Bridgewater			Bedford Street		5750972-1	LRMB	11/20/2004	Plastic	2 "	Like New/Good	Retired	Bare
80	Bridgewater			Bedford Street		5750972-1	LRMB	11/20/2004	Coated Stl 2	2 "	Like New/Good	Exposed	Coal Tar
80	Bridgewater			Bedford Street		5750972-1	LRMB	11/20/2004	Bare Steel 2	2 "	Very Poor	Retired	Bare
80	Bridgewater			Grove Street		5739605-1	LRMB	11/09/2004	Coated Stl 6	6 "	Like New/Good	Exposed	Coal Tar
80	Brockton	130		Liberty Street		5727638-1	LRMB	11/16/2004	Bare Steel 6	6 "	Fair	Exposed	Bare
80	Brockton			N Cary Street		5755224-1	LRMB	11/10/2004	Coated Stl 2	2 "	Like New/Good	Exposed	Coal Tar
80	Brockton			Perkins Avenue		5689180-1	LRMB	11/01/2004	Cast Iron 6	6 "	Like New/Good	Exposed	Bare
80	East Bridgewater			Water Street		574747-1	LRMB	11/24/2004	Bare Steel 2	2 "	Poor	Exposed	Bare
85	Bridgewater			Clarence Ave-summer St		5400169-1	LRMB	11/30/2004	Bare Steel 4	4 "	Poor	Exposed	Bare
85	Bridgewater			Clarence Ave-summer St		5400169-1	LRMB	11/30/2004	Bare Steel 4	4 "	Poor	Retired	Bare
85	Bridgewater			Clarence Ave-summer St		5400169-1	LRMB	11/30/2004	Coated Stl 4	4 "	Like New/Good	New	Coal Tar
85	Bridgewater	273		Summer Street		5428008-1	LRMB	11/30/2004	Bare Steel 2	2 "	Poor	Exposed	Bare
85	Brockton	102	104	Lyman Street		4960067-1	LRMB	11/30/2004	Bare Steel 6	6 "	Poor	Exposed	Bare
85	Brockton	68		Thorny Lea Terrace		5425093-1	LRMB	11/30/2004	Cast Iron 4	4 "	Fair	Exposed	Bare

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Franklin

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Foxboro			Chestnut Street		5733498-1	LRMVB	11/03/2004	Bare Steel	6 "	Poor	Exposed	Bare
80	Foxboro			Main Street		5675954-1	LRMVB	11/22/2004	Bare Steel	2 "	Fair	Exposed	Bare
80	Foxboro	181		Mechanic Street		189738-1	LRMVB	11/22/2004	Coated Stl	4 "	Poor	Exposed	Coal Tar
80	Foxboro			North Street		5721454-1	LRMVB	11/04/2004	Bare Steel	6 "	Poor	Exposed	Bare
80	Foxboro	63		Oak Street		5755281-1	LRMVB	11/27/2004	Bare Steel	4 "	Fair	Exposed	Bare
80	Franklin			Hillside Road		1830804-1	LRMVB	11/29/2004	Bare Steel	2 "	Poor	Exposed	Bare
80	Franklin	46		Ruggles Street		5751839-1	LRMVB	11/27/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
80	Medway	2		Brigham Street		5225448-1	LRMVB	11/01/2004	Bare Steel	2 "	Fair	Exposed	Bare
80	Medway	20		Maple Street		5748740-1	LRMVB	11/19/2004	Bare Steel	3 "	Very Poor	Exposed	Bare
80	Walpole	15		Charles Street		5732337-1	LRMVB	11/10/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
80	Walpole	50		Charlotte Road		5715309-1	LRMVB	11/06/2004	Coated Stl	3 "	Like New/Good	Exposed	Coal Tar
80	Walpole	50		Charlotte Road		5715309-1	LRMVB	11/06/2004	Bare Steel	3 "	Poor	Exposed	Bare
80	Walpole	103		Common Street		5715309-1	LRMVB	11/06/2004	Bare Steel	3 3/4 "	Fair	Retired	Bare
80	Walpole	427		East Street		5683572-1	LRMVB	11/09/2004	Bare Steel	2 "	Poor	Exposed	Bare
80	Walpole	469		Washington Street		5602263-1	LRMVB	11/29/2004	Bare Steel	6 "	Fair	Exposed	Bare
80	Wrentham	720		Franklin		5751884-1	LRMVB	11/26/2004	Bare Steel	4 "	Poor	Exposed	Bare
85	Foxboro	155	157	Mechanic Street		5427810-1	LRMVB	11/30/2004	Bare Steel	4 "	Fair	Exposed	Bare
85	Foxboro			Mechanic Street		5427909-1	LRMVB	11/30/2004	Bare Steel	4 "	Fair	Exposed	Bare
85	Foxboro	121		South Street		5291210-1	LRMVB	11/30/2004	Bare Steel	3 "	Poor	Exposed	Bare
85	Foxboro			Villa Drive		5365338-1	LRMVB	11/30/2004	Coated Stl	2 "	Poor	Exposed	Coal Tar
85	Franklin	2		High Street		5428229-1	LRMVB	11/30/2004	Bare Steel	6 "	Poor	Exposed	Bare
85	Franklin	809		Lincoln Street		5414971-1	LRMVB	11/30/2004	Bare Steel	6 "	Poor	Exposed	Bare
85	Franklin	21		Skyline Drive		5424934-1	LRMVB	11/30/2004	Coated Stl	2 "	Like New/Good	Exposed	Coal Tar
85	Medway			Sanford Street		5431609-1	LRMVB	11/30/2004	Bare Steel	6 "	Poor	Exposed	Coal Tar
85	Walpole	2		Adams Road		5237959-1	LRMVB	11/30/2004	Coated Stl	3 3/4 "	Like New/Good	Exposed	Coal Tar
85	Walpole	39		Chandler Avenue		5400096-1	LRMVB	11/30/2004	Plastic	1/2 "	Like New/Good	Exposed	Coal Tar
85	Walpole	39		Chandler Avenue		5400096-1	LRMVB	11/30/2004	Plastic	1/2 "	Fair	Exposed	Bare
85	Walpole	39		Chandler Avenue		5400096-1	LRMVB	11/30/2004	Plastic	1/2 "	Fair	Retired	Bare
85	Walpole	25		Prospect Street		5394586-1	LRMVB	11/30/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
85	Walpole	1385		Washington Street		1220442-1	LRMVB	11/30/2004	Coated Stl	1 1/4 "	Like New/Good	Exposed	Coal Tar
85	Wrentham	58		Creek Street		5400246-1	LRMVB	11/30/2004	Bare Steel	3 "	Poor	Exposed	Bare
85	Wrentham	609		East Street	Marty	5396813-1	LRMVB	11/30/2004	Bare Steel	6 "	Fair	Exposed	Bare
85	Wrentham	609		East Street		5405836-1	LRMVB	11/30/2004	Bare Steel	6 "	Fair	Exposed	Bare
85	Wrentham	609		East Street		5425170-1	LRMVB	11/30/2004	Bare Steel	6 "	Fair	Exposed	Bare
85	Wrentham	181		Winter Street		5387583-1	LRMVB	11/30/2004	Bare Steel	3 "	Fair	Exposed	Bare

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Hanover	1544		Broadway		5752020-1	LRMB	11/22/2004	Bare Steel 3 "		Poor	Exposed	Bare
80 Hanover	1102		Hanover Street		5733802-1	LRMB	11/03/2004	Plastic 2 "		Fair	Exposed	Bare
80 Marshfield	3		Barna Road		5705449-1	LRMB	11/08/2004	Bare Steel 2 "		Poor	Exposed	Bare
80 Marshfield	627		Careswell Street		5747480-1	LRMB	11/17/2004	Pistc Ins 1/2 "		Like New/Good	New	Bare
80 Marshfield	627		Careswell Street		5747480-1	LRMB	11/17/2004	Bare Steel 4 "		Fair	Exposed	Bare
80 Marshfield	627		Careswell Street		5747480-1	LRMB	11/17/2004	Coated Stl 3/4 "		Like New/Good	Retired	Coal Tar
80 Marshfield	44		Shirley Street		5738569-1	LRMB	11/10/2004	Bare Steel 1 "		Fair	Exposed	Bare
80 Marshfield	44		Shirley Street		5738569-1	LRMB	11/10/2004	Bare Steel 1 "		Fair	Exposed	Bare
80 Scituate			Edgewood Road		5734935-1	LRMB	11/04/2004	Bare Steel 3 "		Poor	Exposed	Bare
80 Scituate	303		Edgewood Road		5745411-1	LRMB	11/15/2004	Bare Steel 3 "		Poor	Exposed	Bare
80 Scituate	154		Gannett Road		5702548-1	LRMB	11/23/2004	Bare Steel 3 "		Poor	Exposed	Bare
80 Scituate	49		Gannett Road		5738574-1	LRMB	11/07/2004	Bare Steel 2 "		Poor	Exposed	Bare
80 Scituate	225		Glades Road		5745313-1	LRMB	11/15/2004	Bare Steel 2 "		Fair	Exposed	Bare
80 Scituate			Stockbridge Road		5753927-1	LRMB	11/24/2004	Bare Steel 4 "		Poor	Exposed	Bare
85 Duxbury			Spring Street		5317383-1	LRMB	11/30/2004	Bare Steel 1 1/4 "		Fair	Exposed	Bare
85 Hanover	135		King Street		5431477-1	LRMB	11/30/2004	Bare Steel 3 "		Fair	Exposed	Bare
85 Hanover	111		Washington Street		5320657-1	LRMB	11/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85 Hanover	199		Washington Street		5405957-1	LRMB	11/30/2004	Bare Steel 2 "		Very Poor	Exposed	Bare
85 Hanson	520		Winter Street		1130352-1	LRMB	11/30/2004	Stnlss Stl 8 "		Fair	Exposed	Bare
85 Marshfield	16		E Street		5400180-1	LRMB	11/30/2004	Coated Stl 1 "		Fair	Exposed	Coal Tar
85 Marshfield	226		Elm Street		5413178-1	LRMB	11/30/2004	Bare Steel 3/4 "		Poor	Exposed	Bare
85 Marshfield	201		Ferry Street		5419697-1	LRMB	11/30/2004	Bare Steel 3 "		Very Poor	Exposed	Bare
85 Marshfield	5		Hyde Way		5398360-1	LRMB	11/30/2004	Bare Steel 2 "		Poor	Exposed	Bare
85 Marshfield	190		Saginaw Avenue		5367724-1	LRMB	11/30/2004	Bare Steel 2 "		Fair	Exposed	Bare
85 Marshfield	149		Tower Avenue		5407044-1	LRMB	11/30/2004	Bare Steel 1 1/2 "		Very Poor	Exposed	Bare
85 Marshfield	19		Winslow Street Extension		5407086-1	LRMB	11/30/2004	Bare Steel 1 1/2 "		Fair	Exposed	Bare
85 Marshfield	19		Winslow Street Extension		5407086-1	LRMB	11/30/2004	Bare Steel 1 1/2 "		Fair	Exposed	Bare
85 Marshfield	19		Winslow Street Extension		5407086-1	LRMB	11/30/2004	Bare Steel 1 1/2 "		Fair	Retired	Bare
85 Norwell	41		Franklin Road		5400146-1	LRMB	11/30/2004	Coated Stl 1 1/2 "		Fair	New	Coal Tar
85 Pembroke	74		Center Street		5328865-1	LRMB	11/30/2004	Coated Stl 2 "		Fair	Exposed	Coal Tar
85 Pembroke	421		High Street		5327917-1	LRMB	11/30/2004	Bare Steel 8 "		Fair	Exposed	Bare
85 Scituate			Brook Street		5330303-1	LRMB	11/30/2004	Coated Stl 2 "		Very Poor	Exposed	Coal Tar
85 Scituate			Brook Street		5367723-1	LRMB	11/30/2004	Bare Steel 4 "		Fair	Exposed	Bare
85 Scituate			Brook Street		5367723-1	LRMB	11/30/2004	Bare Steel 4 "		Poor	Retired	Bare
85 Scituate			Brook Street		5367723-1	LRMB	11/30/2004	Coated Stl 4 "		Like New/Good	New	Bare
85 Scituate	80		Brook Street		5378020-1	LRMB	11/30/2004	Bare Steel 4 "		Fair	Exposed	Bare

Program: wwrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Randolph

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Canton			Neponset Street		5751831-1	LRMVB	11/27/2004	Bare Steel 3 "	"	Fair	Exposed	Bare
80	Canton			Washington		5668294-1	LRMVB	11/09/2004	Bare Steel 3/4 "	"	Poor	Exposed	Bare
80	Easton	24		Main Street		5710652-1	LRMVB	11/02/2004	Bare Steel 1 "	"	Poor	Exposed	Bare
80	Easton	40		Turnpike Street		5702493-1	LRMVB	11/03/2004	Bare Steel 1 1/2 "	"	Fair	Exposed	Bare
80	Easton	320		Washington Street		5752706-1	LRMVB	11/23/2004	Bare Steel 4 "	"	Very Poor	Exposed	Bare
80	Holbrook			Spring Street		5739601-1	LRMVB	11/09/2004	Plastic 2 "	"	Like New/Good	Exposed	Bare
80	Randolph	18		Milton Terrace		5720045-1	LRMVB	11/08/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
80	Sharon	73		Billings Street		5691246-1	LRMVB	11/08/2004	Bare Steel 2 "	"	Fair	Exposed	Bare
80	Sharon	27		Cottage Street		5738080-1	LRMVB	11/08/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
80	Sharon			East Street		5691244-1	LRMVB	11/27/2004	Bare Steel 6 "	"	Fair	Exposed	Bare
80	Sharon	96		Norwood Street		5302047-1	LRMVB	11/30/2004	Bare Steel 2 "	"	Very Poor	Exposed	Bare
80	Stoughton	82		Canton Street		5747484-1	LRMVB	11/26/2004	Bare Steel 1 1/4 "	"	Fair	Exposed	Bare
80	Stoughton	82		Canton Street		5747484-1	LRMVB	11/26/2004	Bare Steel 4 "	"	Fair	Exposed	Bare
80	Stoughton	82		Canton Street		5747484-1	LRMVB	11/26/2004	Bare Steel 1 1/4 "	"	Very Poor	Retired	Bare
80	Stoughton			Central Street		5710654-1	LRMVB	11/17/2004	Bare Steel 6 "	"	Fair	Exposed	Bare
80	Stoughton	345		Cushing Street		5709368-1	LRMVB	11/17/2004	Bare Steel 1 1/4 "	"	Fair	Exposed	Bare
80	Stoughton			Monk Street		5746500-1	LRMVB	11/16/2004	Bare Steel 2 "	"	Fair	Exposed	Bare
80	Stoughton			Ralph Mann Drive		5406989-1	LRMVB	11/22/2004	Bare Steel 2 "	"	Very Poor	Exposed	Bare
85	Easton	9		Hollis Road		5351588-1	LRMVB	11/30/2004	Bare Steel 1 1/2 "	"	Fair	Exposed	Bare
85	Easton	9		Hollis Road		5351588-1	LRMVB	11/30/2004	Bare Steel 1 "	"	Very Poor	Retired	Bare
85	Holbrook	170		S Franklin Street		533942-1	LRMVB	11/30/2004	Bare Steel 6 "	"	Poor	Exposed	Bare
85	Holbrook			S Franklin Street	399	5396004-1	LRMVB	11/30/2004	Bare Steel 6 "	"	Poor	Exposed	Bare
85	Holbrook	322		South Street		5314670-1	LRMVB	11/30/2004	Plastic 1/2 "	"	Like New/Good	Exposed	Bare
85	Holbrook	322		South Street		5314670-1	LRMVB	11/30/2004	Plastic 1/2 "	"	Like New/Good	Exposed	Bare
85	Holbrook	211		South Street		5337748-1	LRMVB	11/30/2004	Bare Steel 6 "	"	Fair	Exposed	Coal Tar
85	Randolph	239		Grove Street		5394372-1	LRMVB	11/30/2004	Coated Stl 2 "	"	Poor	Exposed	Bare
85	Randolph	13		N Harriette Street		5407035-1	LRMVB	11/30/2004	Bare Steel 1 1/4 "	"	Poor	Exposed	Bare
85	Randolph			N Main Street		5275163-1	LRMVB	11/30/2004	Bare Steel 2 "	"	Like New/Good	Exposed	Bare
85	Randolph	8		S Harriette Street		5418887-1	LRMVB	11/30/2004	Bare Steel 1 1/4 "	"	Very Poor	Exposed	Bare
85	Randolph	133		Union Street		5256147-1	LRMVB	11/30/2004	Coated Stl 2 "	"	Like New/Good	Exposed	Coal Tar
85	Randolph	133		Union Street		5356147-1	LRMVB	11/30/2004	Coated Stl 2 "	"	Like New/Good	Retired	Coal Tar
85	Randolph	133		Union Street		5356147-1	LRMVB	11/30/2004	Plastic 2 "	"	Like New/Good	New	Bare
85	Sharon	69		Moose Hill Parkway		5302044-1	LRMVB	11/30/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
85	Sharon	69		Moose Hill Parkway		5424201-1	LRMVB	11/30/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
85	Stoughton	1170		Central Street		5434212-1	LRMVB	11/30/2004	Bare Steel 4 "	"	Poor	Exposed	Bare
85	Stoughton	50		Charles Circle		5367722-1	LRMVB	11/30/2004	Bare Steel 2 "	"	Poor	Exposed	Bare
85	Stoughton	50		Charles Circle		5367722-1	LRMVB	11/30/2004	Bare Steel 1 "	"	Poor	Retired	Bare
85	Stoughton	50		Charles Circle		5367722-1	LRMVB	11/30/2004	Plastic 1/2 "	"	Like New/Good	New	Bare
85	Stoughton	333		Cushing Street		5413243-1	LRMVB	11/30/2004	Bare Steel 1 1/4 "	"	Poor	Exposed	Bare
85	Stoughton	1334		Park Street		5428003-1	LRMVB	11/30/2004	Bare Steel 4 "	"	Poor	Exposed	Bare
85	Stoughton	75		Rockland Street		5427780-1	LRMVB	11/30/2004	Bare Steel 1 1/2 "	"	Fair	Exposed	Bare

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Attleboro	369	389	Newport Avenue		572363-1	LRMVB	11/17/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
80 Attleboro	2		Oakhill Avenue		5750219-1	LRMVB	11/19/2004	Coated Stl 1 1/4 "	1 1/4 "	Fair	Exposed	Coal Tar
80 Attleboro	4		Yale Street		5750002-1	LRMVB	11/20/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
80 Seekonk			Perrin Avenue		5035276-1	LRMVB	11/25/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
80 Seekonk			Plainfield Street		5025963-1	LRMVB	11/25/2004	Coated Stl 2 "	2 "	Fair	Exposed	Coal Tar
80 Taunton	120		Ingeil Street		5750078-1	LRMVB	11/19/2004	Coated Stl 1 1/2 "	1 1/2 "	Fair	Exposed	Coal Tar
85 Attleboro	55		Alder Street		5430383-1	LRMVB	11/30/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85 Attleboro	11		Hazel Street		5394579-1	LRMVB	11/30/2004	Coated Stl 4 "	4 "	Like New/Good	Exposed	Coal Tar
85 Mansfield			Church Street		5429144-1	LRMVB	11/30/2004	Bare Steel 3/4 "	3/4 "	Fair	Exposed	Bare
85 Mansfield	29		Henry Street		5434219-1	LRMVB	11/30/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85 Mansfield	215		N Main Street		5373998-1	LRMVB	11/30/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare
85 Norton			Mansfield Avenue		5413283-1	LRMVB	11/30/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
85 Norton	274		S Worcester Street		5413097-1	LRMVB	11/30/2004	Bare Steel 8 "	8 "	Fair	Exposed	Bare
85 Norton	153		W Main Street		5428038-1	LRMVB	11/30/2004	Bare Steel 6 "	6 "	Fair	Exposed	Bare
85 Seekonk			Bloomfield Street		5427759-1	LRMVB	11/30/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
85 Seekonk	55		Coleman Street		5390798-1	LRMVB	11/30/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85 Seekonk	133		Jacob Street		5404186-1	LRMVB	11/30/2004	Bare Steel 4 "	4 "	Poor	Exposed	Bare
85 Taunton	93		Fisher Street		5389214-1	LRMVB	11/30/2004	Bare Steel 8 "	8 "	Fair	Exposed	Bare
85 Taunton	308		Somerset Avenue		5391379-1	LRMVB	11/30/2004	Cast Iron 6 "	6 "	Very Poor	Exposed	Bare

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 146 Orders in this report.

Bay State Gas Company
Work Order Management System
Pipe Condition Report

End of Report

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver

=====

R E P O R T P A R A M E T E R S

=====

Report Type : All
Division : Brockton
District : (All)
Town : (All)
Work Type : Distribution
Work Category : Leaks
Work Code : Main - Leak Repair
Project ID :
Output # : 0000
Status From :
Status To :
From Date : 12/01/2004
To Date : 12/31/2004
Pipe Type : (All)
Pipe Size : (All)
Pipe Condition : (All)
Pipe Action : (All)
Pipe Coating : (All)

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Brockton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Brockton	28		Bunker Avenue		5752922-1	LRMXB	12/06/2004	Cast Iron 4 "	4 "	Like New/Good	Exposed	Bare
80	Brockton	34		Davids Street		5783285-1	LRMXB	12/28/2004	Cast Iron 4 "	4 "	Poor	Exposed	Bare
80	Brockton	39		Forest Road		5787165-1	LRMXB	12/31/2004	Wright Iron 2 "	2 "	Fair	Exposed	Bare
80	Brockton	21		Provost Street		5775050-1	LRMXB	12/17/2004	Plastic 1 "	1 "	Like New/Good	New	Bare
80	Brockton	21		Provost Street		5775050-1	LRMXB	12/17/2004	Plastic 1/2 "	1/2 "	Like New/Good	Exposed	Bare
80	Brockton	21		Provost Street		5775050-1	LRMXB	12/17/2004	Plastic 1/2 "	1/2 "	Like New/Good	Retired	Bare
80	Brockton	123		Summer Street		5762344-1	LRMXB	12/03/2004	Bare Steel 6 "	6 "	Very Poor	Exposed	Bare
80	Brockton	112		Summer Street		5765632-1	LRMXB	12/14/2004	Bare Steel 8 "	8 "	Fair	Exposed	Bare
80	Brockton	93		Summer Street		576502-1	LRMXB	12/08/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	Brockton			River Street		5440477-1	LRMXB	12/31/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
85	Brockton	35		Sprague Avenue		5440663-1	LRMXB	12/31/2004	Cast Iron 6 "	6 "	Fair	Exposed	Bare
85	Brockton	99		Warren Avenue		5448859-1	LRMXB	12/31/2004	Cast Iron 4 "	4 "	Fair	Exposed	Bare
85	West Bridgewater	20		Charles Street		5452509-1	LRMXB	12/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	West Bridgewater	20		Charles Street		5452519-1	LRMXB	12/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	West Bridgewater	19		High Street		5472699-1	LRMXB	12/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare
85	West Bridgewater	448		N Elm Street		5359910-1	LRMXB	12/31/2004	Bare Steel 3 "	3 "	Poor	Exposed	Bare
85	West Bridgewater	380		Spring Street		5448600-1	LRMXB	12/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare

Program: wwrpt031.p
 Date: 06/23/2005
 Reg By: Katherine Silver
 DISTRICT: Franklin

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Bellingham			Hartford Avenue		5756279-1	LRMVB	12/17/2004	Coated Stl 4 "		Like New/Good	Exposed	Coal Tar
80	Foxboro			Main Street		5314716-1	LRMVB	12/03/2004	Bare Steel 6 "		Very Poor	Exposed	Bare
80	Foxboro			North Street		5769783-1	LRMVB	12/14/2004	Bare Steel 6 "		Very Poor	Exposed	Bare
80	Franklin			Pleasant Street		374868-1	LRMVB	12/03/2004	Bare Steel 3 "		Poor	Exposed	Bare
80	Franklin	75		Pleasant Street		5767664-1	LRMVB	12/09/2004	Bare Steel 3 "		Poor	Exposed	Bare
80	Medway	9		Oakland Street		5753834-1	LRMVB	12/04/2004	Bare Steel 3 "		Poor	Exposed	Bare
80	Walpole	12		Towle Road		5771188-1	LRMVB	12/14/2004	Coated Stl 2 "		Fair	Exposed	Bare
80	Walpole	1480		Washington Street		4752726-1	LRMVB	12/28/2004	Plastic 1/2 "		Like New/Good	Exposed	Coal Tar
80	Wrentham	181		Winter Street		5771606-1	LRMVB	12/18/2004	Bare Steel 3 "		Poor	Exposed	Bare
85	Franklin	54		Fisher Street		5413279-1	LRMVB	12/31/2004	Bare Steel 3 "		Very Poor	Exposed	Bare
85	Franklin			Lincoln Street		5440868-1	LRMVB	12/31/2004	Bare Steel 6 "		Poor	Exposed	Bare
85	Walpole	9		Water Street		5432624-1	LRMVB	12/31/2004	Bare Steel 6 "		Poor	Exposed	Bare
85	Wrentham	609		East Street		5442951-1	LRMVB	12/31/2004	Bare Steel 6 "		Very Poor	Exposed	Bare

Program: wrpt011.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Hanover

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Duxbury	5		Lovers Lane		5626720-1	LRMVB	12/21/2004	Bare Steel	1 1/2 "	Fair	Exposed	Bare
80 Hanson	122		W Washington Street		5763344-1	LRMVB	12/04/2004	Bare Steel	8 "	Poor	Exposed	Bare
80 Hanson	168		Winter Street		5781585-1	LRMVB	12/25/2004	Bare Steel	1 "	Like New/Good	Exposed	Bare
80 Marshfield	36		Landing Road		5781506-1	LRMVB	12/31/2004	Coated Stl	2 "	Fair	Exposed	Coal Tar
80 Pembroke	120		Center Street		5779384-1	LRMVB	12/19/2004	Bare Steel	4 "	Very Poor	Exposed	Bare
80 Pembroke	13		Pondview Avenue		5758062-1	LRMVB	12/04/2004	Bare Steel	1 1/2 "	Fair	Exposed	Bare
80 Scituate	11		Conroy Terrace		5778153-1	LRMVB	12/22/2004	Bare Steel	1 1/2 "	Poor	Exposed	Bare
80 Scituate	11		Conroy Terrace		5778153-1	LRMVB	12/22/2004	Bare Steel	1 1/2 "	Fair	Retired	Bare
80 Scituate	22		Greenfield Lane		5767646-1	LRMVB	12/09/2004	Bare Steel	1 1/2 "	Poor	Exposed	Bare
85 Duxbury			Bay Road		5345872-1	LRMVB	12/31/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
85 Duxbury			Elm Street		5359983-1	LRMVB	12/31/2004	Bare Steel	2 "	Fair	Exposed	Bare
85 Duxbury	63		Upland Road		5407038-1	LRMVB	12/31/2004	Bare Steel	2 "	Very Poor	Exposed	Bare
85 Marshfield	24		Fourth Road		5440440-1	LRMVB	12/31/2004	Bare Steel	1 1/2 "	Very Poor	Exposed	Bare
85 Norwell	45		Dana Road		5360323-1	LRMVB	12/31/2004	Bare Steel	2 "	Fair	Exposed	Bare
85 Norwell	47		Wilder Road		5351597-1	LRMVB	12/31/2004	Bare Steel	2 "	Fair	Exposed	Bare
85 Pembroke	517		Mattakesett Street		5351665-1	LRMVB	12/31/2004	Bare Steel	4 "	Very Poor	Exposed	Bare
85 Pembroke	36		School Street		5442763-1	LRMVB	12/31/2004	Bare Steel	2 "	Very Poor	Exposed	Bare

Program: wrpt031.P
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Randolph

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat Town Name	At	To Lot	Street Name	Contact Name	Work Order	Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80 Canton	90		Lawrence Street		5779239-1	LRMYB	12/19/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
80 Randolph	33		Rockefeller Street		5756424-1	LRMYB	12/02/2004	Bare Steel 2 "	2 "	Very Poor	Exposed	Bare
80 Randolph	19		Rockefeller Street		5772630-1	LRMYB	12/15/2004	Bare Steel 2 "	2 "	Fair	Exposed	Bare
80 Sharon	61		Brook Road		5727681-1	LRMYB	12/04/2004	Bare Steel 1 1/4 "	1 1/4 "	Very Poor	Exposed	Bare
80 Stoughton			Canton Street		5702552-1	LRMYB	12/11/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
80 Stoughton			Canton Street		5773832-1	LRMYB	12/18/2004	Bare Steel 6 "	6 "	Poor	Exposed	Bare
80 Stoughton			Central Street		5527768-1	LRMYB	12/14/2004	Bare Steel 1 1/2 "	1 1/2 "	Like New/Good	Exposed	Bare
80 Stoughton	31		Rockland Street		5766389-1	LRMYB	12/11/2004	Bare Steel 1 1/4 "	1 1/4 "	Very Poor	Exposed	Bare
80 Stoughton			Rockland Street		5771182-1	LRMYB	12/14/2004	Bare Steel 1 1/4 "	1 1/4 "	Fair	Exposed	Bare
85 Canton	14		Greenbriar Road		5425332-1	LRMYB	12/31/2004	Coated Stl 2 "	2 "	Poor	Exposed	Bare
85 Holbrook	344		S Franklin Street		5450659-1	LRMYB	12/31/2004	Bare Steel 6 "	6 "	Very Poor	Exposed	Bare
85 Randolph			Lawson Street		5428704-1	LRMYB	12/31/2004	Bare Steel 1 1/4 "	1 1/4 "	Poor	Exposed	Bare
85 Sharon	143		Ames Street		5435475-1	LRMYB	12/31/2004	Bare Steel 2 "	2 "	Poor	Exposed	Bare

Program: wrpt031.p
 Date: 06/23/2005
 Req By: Katherine Silver
 DISTRICT: Taunton

Bay State Gas Company
 Work Order Management System
 Pipe Condition Report

Stat	Town Name	At	To Lot	Street Name	Contact Name	Work Order Code	Date	Pipe Type	Pipe Size	Pipe Condition	Pipe Action	Pipe Coating
80	Attleboro	40		Lawn Street		5779284-1	LRMB	12/19/2004	Bare Steel 2 "	Very Poor	Exposed	Bare
80	Attleboro			Locust Street		5771445-1	LRMB	12/12/2004	Bare Steel 2 "	Poor	Exposed	Bare
80	Attleboro	58		Old Stagecoach Road		5776037-1	LRMB	12/13/2004	Bare Steel 3 "	Poor	Exposed	Bare
80	Seekonk	44		Hope Street		5771276-1	LRMB	12/17/2004	Bare Steel 2 "	Very Poor	Exposed	Bare
80	Taunton			Chandler Avenue		5769785-1	LRMB	12/11/2004	Cast Iron 3 "	Fair	Exposed	Bare
80	Taunton	72		Grant Street		5787143-1	LRMB	12/31/2004	Cast Iron 4 "	Fair	Exposed	Bare
80	Taunton	24		Hart Street		5774131-1	LRMB	12/14/2004	Wright Iron 6 "	Poor	Exposed	Bare
80	Taunton	24		Hart Street		5779321-1	LRMB	12/22/2004	Wright Iron 6 "	Poor	Exposed	Bare
80	Taunton	208		Highland Street		5782224-1	LRMB	12/27/2004	Bare Steel 8 "	Very Poor	Exposed	Bare
80	Taunton	120		Ingell Street		5784428-1	LRMB	12/36/2004	Coated Stl 1 1/2 "	Fair	Exposed	Coal Tar
80	Taunton	34	36	N Walker Street		5781504-1	LRMB	12/28/2004	Bare Steel 8 "	Poor	Exposed	Bare
80	Taunton	351		Somerset Avenue		5857693-1	LRMB	12/29/2004	Cast Iron 14 "	Like New/Good	Exposed	Bare
80	Taunton	427		Winthrop Street		5760317-1	LRMB	12/02/2004	Bare Steel 2 "	Very Poor	Exposed	Bare
85	Mansfield			Blake Place		5378241-1	LRMB	12/31/2004	Coated Stl 3 3/4 "	Poor	Exposed	Coal Tar
85	Mansfield			Blake Place		5378241-1	LRMB	12/31/2004	Bare Steel 3 3/4 "	Very Poor	Retired	Bare
85	Mansfield	16		Dean Street		5456430-1	LRMB	12/31/2004	Bare Steel 2 "	Poor	Exposed	Bare
85	Mansfield	65		Fruit Street		1222479-1	LRMB	12/31/2004	Coated Stl 1 "	Like New/Good	Exposed	Coal Tar
85	Mansfield			Shawmut Avenue		5394584-1	LRMB	12/31/2004	Coated Stl 2 "	Like New/Good	Exposed	Coal Tar
85	Mansfield	48		Warren Avenue		5365363-1	LRMB	12/31/2004	Bare Steel 2 "	Fair	Exposed	Bare
85	Mansfield			Warren Avenue		5365370-1	LRMB	12/31/2004	Bare Steel 2 "	Poor	Exposed	Bare
85	Norton	81	83	S Worcester Street		5430316-1	LRMB	12/31/2004	Bare Steel 8 "	Like New/Good	Exposed	Bare
85	Raynham	1305		N Main Street		5452422-1	LRMB	12/31/2004	Plastic 4 "	Like New/Good	Exposed	Bare
95	Seekonk	336		Anthony Street		5428965-1	LRMB	12/31/2004	Plastic 1 1/2 "	Like New/Good	Exposed	Bare
85	Seekonk	336		Anthony Street		5428965-1	LRMB	12/31/2004	Plastic 1 1/2 "	Like New/Good	Exposed	Bare
85	Seekonk			Bloomfield Street		5436085-1	LRMB	12/31/2004	Bare Steel 2 "	Fair	Exposed	Bare
85	Seekonk	31		Bloomfield Street		5436085-1	LRMB	12/31/2004	Bare Steel 2 "	Fair	Retired	Bare
85	Seekonk	31		Bloomfield Street		5445816-1	LRMB	12/31/2004	Plastic 2 "	Fair	Exposed	Bare
85	Seekonk	25		Bloomfield Street		5445816-1	LRMB	12/31/2004	Plastic 2 "	Fair	Retired	Bare
85	Seekonk	1524		Leigh Street		5456244-1	LRMB	12/31/2004	Bare Steel 2 "	Fair	Exposed	Bare
85	Taunton	605		Somerset Avenue		5327985-1	LRMB	12/31/2004	Bare Steel 6 "	Like New/Good	Exposed	Bare
85	Taunton			W Water Street		5437321-1	LRMB	12/31/2004	Coated Stl 4 "	Fair	Exposed	Coal Tar

Bay State Gas Company
Work Order Management System
Pipe Condition Report

Program: wwrpt031.p
Date: 06/23/2005
Req By: Katherine Silver
There are 92 Orders in this report.

End of Report

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY-SEVENTH SET OF INFORMATION REQUESTS FROM ATTORNEY
GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: John E. Skirtich, Consultant (Revenue Requirements)

AG-27-12 Referring to the response to Information Request AG-3-28, please
indicate the square footage associated with the vacant floor at each site.

Response: In the Westborough building, there is 23,665 square feet of rentable
space. There is no rentable space in any other locations.

COMMONWEALTH OF MASSACHUSETTS
DEPARTMENT OF TELECOMMUNICATIONS AND ENERGY

RESPONSE OF BAY STATE GAS COMPANY TO THE
TWENTY-SEVENTH SET OF INFORMATION REQUESTS FROM ATTORNEY
GENERAL
D. T. E. 05-27

Date: June 27, 2005

Responsible: Paul Moul, Consultant (ROE)

AG-27-19 Referring to the Company's response to Information Request AG-10-30, please provide a complete copy of the SBBI "Stocks, Bonds, Bills, and Inflation, 2005 Yearbook, Market Results for 1926 - 2004," as was requested in the original Information Request.

Response: Mr. Moul only relied upon the pages that were provided in the response to AG-10-9. To duplicate the entire SBBI Yearbook (a copyrighted publication) would be unduly burdensome because the Yearbook is 359 pages in length.